Certificate of Location of Government Corner

ID#: 630406 **Description:** 1/4 SEC COR 4 5 63 **Date Set:** 8/9/1976 **County:** Olmsted

Section: 04 **Township:** 106N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls in old E-W fence and 10' west of old CP
Punch cross in N side 4"steel post (up 3 1/2') E 83.55'
Bottle Cap in E side 29" Maple SE 44.46'
Bottle Cap in E side 29" Maple SW 38.74'
Post w/sign 1' north
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes: William A. Jones, Deputy Surveyor; South on true line between sections 4 & 5. 39.42 chs set post at quarter section corner. Deposited charcoal, Made mound, trench with pits, and planted cherry seeds NE & SW.. 79.42 chs to section corner.

4-1875 Thomas Hunter (Pg 333 No 327), County Surveyor, found a stone by the post remains in the center of the road. Measured 2655.84' East to the center of section 4. Set the 1/16 East midway and on line.

1929 John Kerr (Bk 2 P 47), County Surveyor, records stone and post at the corner and a measure East of 2645.5'.

6-1935 county highway department (B 75 Pg 8) found a 2"x6"x12" limestone. Measured east to the corner post at the center of Section 4 (2655.3').

1948 John Kerr (Bk 38 Pg 64) records a stone marked with a cross and post at the corner. Measured 2642.6' East to the Center of Section 4 and set the 1/16 East as 1321.3'. (Found a stone at the 1/16 East at 1316.6' but didn't accept as the 1/16.

1950 John Kerr (Bk 47 Pg 77) records a 1/2" steel rod at the 1/16 East 6.4' East of the fence South.

6-15-1965 J. Kerr set CIM with iron below

11-22-1972 County Surveyor found the stone which was found by the county highway department 10.7' west and .5' north of Kerr CIM.

8-9-1976 County Surveyor accepted the stone found in 1972 as Hunter's corner since it fit Hunter's measure to the fence at the 1/16 East and to the corner post at the Center of Section 4. Set a 1/2"x2' rod on the South side of the stone and a C.I.M. over the stone. Removed Kerr's C.I.M. which was 10.75' East and .65' South of the correct corner.

5-25-1989 County Surveyor found CIM in good condition. Used in City of Rochester mapping project survey.

12-1-2003 County Surveyor found CIM up 0.1' in good condition.