Certificate of Location of Government Corner

ID#: 630504 **Description:** 1/4 SEC COR 5 8 63 **Date Set:** 10/4/2007 **County:** Olmsted

Section: 05 **Township:** 106N **Range:** 13W **Monument Description:** 1" copper plug w/punch mark RLS #15809

Reference Ties:

The corner falls in center median of Towne Club Parkway SE, 1.2' west of east TBC and 1.8' north of north edge median nose
County Survey Disk in S side PP #23650 WNW 130.63'
County Survey Disk in W side LP #23393 NNE 67.36'
This corner is located by GPS reference stations "Towne Club A & B"

Corner History:

1853 Gov't Notes, William Jones; 39.91 set a post at 1/4 section post. Deposited charcoal, made mound, trench, pits, and planted cherry seeds NE & SW.

? Corner gone , replaced. 16 east set stake, 16 west set stake.

1932 county highway department Bk.64 Pg.75; New ties to cross on top of stone. Ties- button in telephone pole NW 42.3', button in telephone pole SSW 111.6'. Note: could be wrong corner (sec 35?)

5-1963 J. Kerr set CIM in place of iron rod. RPs- disc in pp NE 124.9', disc in pp NW 149.7'.

3-13-1989 County Surveyor dug down 18" to CIM. Set 16" CIM flush in blacktop, centerline of golf course driveway west 80.0'.

12-4-2003 County Surveyor found CIM at surface in good condition.

5-17-2006 County Surveyor removed monument in vacated portion of Eastwood Road for construction of Rochester Towne Club subdivision.

10-4-2007 County Surveyor set 1" copper plug w/punch mark at surface from GPS and traverse data.