Certificate of Location of Government Corner

ID#: 630606 **Description:** W 1/4 SEC COR 6 63 **Date Set:** 11/7/1984 **County:** Olmsted

Section: 06 **Township:** 106N **Range:** 13W **Monument Description:** Chisel marks on manhole ring

Reference Ties:

County Survey Disk in PP #03220 SW 59.46'
PK nail in curb joint near top NW 25.44'
County Survey Disk in LP #11362 SE 56.62'
This corner is located by GPS reference stations "Homestead A & B"

Corner History:

1853 Gov't Notes John Ball, Deputy Surveyor; North between sections 1 & 6. 40.00 chs. Set quarter section post. RPs; Burr oak 10" N53 °W 266 links, dug trench per instructions.

6-1896 William Fraser (by Hunter Pg. 603, No. 548) assumed the corner to be the corner of fences running North and East.

11-29-1977 County Surveyor, there was a large concrete monument in place at this corner for many years prior to the sewer construction. References were taken to this monument by McGhie & Betts. County Surveyor referenced a point (accepted as the corner) on a manhole cover at the intersection of a line from a punch mark in the West side of manhole ring to a punch mark in the East side of the ring and a line from a punch mark in the North side of the manhole ring to a punch mark in the South side of the ring. This point was established from the reference points of McGhie & Betts. Tied out corner since street being graded. Drove 3/4"x30" shaft 2 1/2' south of south edge of 32" cottonwood SW 56.18.

11-7-1984 County Surveyor found 2 sets of chisel marks on manhole ring. One set large and the other small. Used smaller set point shot since it fit tie to RPs iron SW. Large mark intersected .12 NE ly. RPs-PK nail in curb joint near top NW 25.44, PK nail in curb joint near top SW 26.03.

3-9-1989 County Surveyor found marks on manhole. Used corner for City of Rochester mapping project survey.

10-7-2002 County Surveyor found smaller set of chisel marks on manhole ring.

1-7-2004 County Surveyor found smaller set of chisel marks on manhole ring and reinforced. Crossed out wrong set of marks.

2-26-2010 Ken Manahan, Mn/DOT Crew Chief, found chisel marks on manhole ring.