Certificate of Location of Government Corner

ID#: 630804 **Description:** 1/4 SEC COR 8 17 63 **Date Set:** 7/19/2005 **County:** Olmsted

Section: 08 **Township:** 106N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CR 143
The monument is down 0.7'
NW corner house SW 134.8'
County Survey Disk in E side PP #18623 N 32.75'
County Survey Disk in W side PP N 32.12'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, William Jones; 40.0 set post at 1/4 section post. RPs- 9" burr oak N 34° E77, 6" burr oak S1 E277. 5-1871 Perry by Hunter Pg.183 No.194; found corner stake standing, set stone 3x4x24 in its place.

7-1872 T.Hunter Fieldbook 2 Pg.5-6; found stake as set from witness trees.

1947 J.Kerr Pg.4 Bk.33; found stone. 16 west set pipe. RP to 1/4 8-17- 1" iron pipe in fence line SW 40.0, Property corner rod in fence line N 33.0, 1" iron pipe in fence line S 36.0.

7-1965 J. Kerr reset CIM. RPs-1" pipe in fence line South 32.98 ft, Disc in P.P. South 32.8 ft., Disc in P.P. North 32.0 ft., Broken off T post in yard S.W. 42.45 ft, NW corner house SW 134.8, Punched cross in south end culv.SE 42.48,Punched cross in north end culv. NE 45.30.

5-22-1989 County Surveyor found CIM in centerline of CR# 143 in new blacktop.

11-25-2003 County Survey Crew found Cast Iron Monument down 1' in good condition.

7-19-2005 County Survey Crew found Cast Iron Monument with head broken down 1.1', took local ties and removed. Set 1" square pipe w/cap at surface in centerline of CR 143. Updated all ties, found 1" pipe but falls behind PP. Monument falls in centerline of CR 143.

6-2-2017 County Survey Crew found 1" square pipe w/cap at surface in good condition. Lowered pipe 0.6' prior to bituminous mill and overlay.