Certificate of Location of Government Corner

ID#: 630909 **Description:** SEC CEN 9 63 **Date Set:** 5/27/1994 **County:** Olmsted

Section: 09 **Township:** 106N **Range:** 13W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
5/8" pipe w/cap RLS #8952

Reference Ties:

The corner falls 1 1/2' south of E-W fence and 2' east of fence north
This corner is located by GPS reference stations "Heppelmann A & B"

Corner History:

4-9-1875 T. Hunter Pg.267 No.265; Set stake at true inters of right lines.

1927 J.Kerr Bk.3 Pg.37; Set stake 3x3x4 1/2' with shell rock piled around it. RPs- 10" pin oak SE 6', 10" pin oak NNW 5.1', lies 12' east of old fence and 76' norht of fence running west, stake down 3 1/2'.

4-1938 J.Kerr Bk.12 Pg.62; Found stake set 1927.

9-7-1951 J. Kerr, Bk. 52 Pg. 60; found stake.

6-20-1989 County Surveyor found 1" pipe 6" above ground 0.3 south of corner post to fences E-W-N. Set 5/8" ref. Rod 101.06' NE

5-27-1994 Roger Brand & Associates set 5/8" iron pipe/cap at intersecting quarter lines.

9-28-1999 Roger Brand & Associates found and used 5/8" pipe.

12-11-2003 County Surveyor found 1" pipe up 0.5' in good condition and found 5/8" pipe w/cap RLS #8952 up 0.3' in good condition. 5/8" pipe falls 2' East and 1' South of 1" pipe.

8-3-2005 County Surveyor found 5/8" pipe w/cap #8952 and 1" pipe at fence corners. Both pipes are in good condition.

1-10-2006 County Surveyor determined that 1" pipe was incorrect and removed.

4-17-2006 Roger Brand & Associates found and used 5/8" pipe.