Certificate of Location of Government Corner

ID#: 631004 **Description:** 1/4 SEC COR 10 15 63 **Date Set:** 8/21/1963 **County:** Olmsted

Section: 10 **Township:** 106N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The monument is down 1.3'
The corner falls in centerline of CR 143 and 32 1/2' east of centerline of Creekwood Ct SE north
County highway disk in PP S 101.2'
Nail in 8" Oak SE 73.6'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, William Jones; 40.05 1/2 set post at 1/4 section corner. RPs- 8" burr oak S8°E 41links, 10" burr oak N46°W 69links.

5-17-1949 John Kerr, Bk.41 Pg.64; angle iron & stones around (No indication if found or set). RPs- 120d spike in 14" pin oak 50.25'N, pipe n 28.9', pipe s 24.7'.

8-3-1959 John Kerr, Book 75, Page 44, found angle iron with 2" pipe.

8-21-1963 J. Kerr set CIM over rod. RPs-Disc in corner fence post North 43.0', Disc in P.P. South 101.2', Nail in 8" Oak S.E. 73.6'.

5-4-1989 County Surveyor located corner with metal locator and paint marked the spot for further work.

7-29-2004 County survey crew found pk nail at surface. Removed pk nail and found CIM down 1.3' in good condition. Set 1" square pipe w/cap at surface over CIM.

6-23-2008 County survey crew found 1" square pipe w/cap at surface in good condition.

8-8-2013 County survey crew found 1" square pipe with cap at surface in good condition. Removed for 2013 bituminous road overlay. Found cast iron monument directly below down 1.3'. Left the cast iron monument inplace.