Certificate of Location of Government Corner

ID#: 631006 **Description:** 1/4 SEC COR 9 10 63 **Date Set:** 11/14/1994 **County:** Olmsted

Section: 10 **Township:** 106N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #42638

Reference Ties:

The monument is down 0.7'
The corner falls 2' west of centerline of CSAH 11 and 2' south of fence west
Bottle cap in E side PP #21047 NNW 112.4'
Ref pipe NNW 158.09'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, William Jones; 40.0 set section post at 1/4 section corner. RPs- 8" burr oak N14 E196, 7" burr oak N41 W11.

4-1875 T. Hunter Pg.207 No.265; Found small unmarked stake at edge of slough and stumps of 2 bearing trees. Tested with bearing tree notes and found stake to be correct.

1927 J. Kerr, Bk.3 Pg.36; Set stone 2x24x30 as E 1/4 9.

1951 J. Kerr, Bk.52 Pg.60; Corner limeston with pipe riser.

1959 J. Kerr, Bk.75 Pg.44; Stone & pipe corner lies 12.91' west of direct line.

8-4-1969 J. Kerr found pipe and placed short CIM on top. RPs-East to center line of road 3.2', NNW nail and disc in, powerpole,112.4', West spike in corner fence post 26.5'.

5-17-1989 County Surveyor found C.I.M. in good condition.

6-22-1994 County highway crew referenced C.I.M. for road resurfacing.

11-14-1994 County Highway Department set 1" square pipe w/cap at surface from 1994 overlay tie out.

2-23-1999 County Surveyor found 1" square pipe w/cap at surface in good condition.

12-5-2003 County Surveyor found 1" square pipe w/cap at surface in good condition.

6-23-2008 County survey crew found 1" square pipe w/cap at surface in good condition.

3-7-2012 County survey crew found 1" square pipe with cap at the surface in good condition. Lowered pipe and replaced cap in preparation for bituminous road overlay.