Certificate of Location of Government Corner

ID#: 631206 **Description:** 1/4 SEC COR 11 12 63 **Date Set:** 6/5/1964 **County:** Olmsted

Section: 12 **Township:** 106N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 2' south of E-W fence and 3' east of fence north
Center 24" Burr Oak W 4 1/2'
Post w/sign 1' north
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, William Jones, Deputy Surveyor; North 40.0 set post at 1/4 section corner. Bearing trees- 5" red oak N87S. 49° E. 50.3 feet to center of 16" Burr Oak tree
S. 20° 45' West 67.5 feet to center of 16" Burr Oak tree
N. 70°30' East 142.85 feet to spike in Power pole No. D110 (gone 1993)E 45 links, 4" burr oak S62°W 126 links.

12-1910 Charles Larson Pg.142; found boulder set limestone. 16 north set iron stake.

1935 county highway department Bk.87 Pg.73; found boulder in center of pile of small limestone on line with E & W fences.

1946 J. Kerr, Bk.30 Pg.52; Found boulder as corner.

1953 J. Kerr, Caption Bk.30 Pg.52; Found boulder agone, but stone chips and impression of corner as it had laid.

6-8-1962 J. Kerr, BK 85 Pg 35, Meas. East, west, and north.

1964 J. Kerr set CIM. CIM lies nearly under fence running east, about 3° east of fence running north. RPs- center 15" burr oak W. 4.7'.

6-1982 County Surveyor at 1/16th north found T.H. 14 R/W monument lying down 6' Wly of McGhie's pipe and cap. Both approx. 50' north of centerline T.H.14. Dipped all around, but couldn't find Larson's iron. The R/W monument would be in line with the fence south on the south side of the highway and the R/W map shows the fence went east here also.

6-5-1987 County Surveyor dug and found nothing.

10-19-2006 County Surveyor found CIM down 0.1' in good condition. Set post w/sign.