Certificate of Location of Government Corner

ID#: 631305 **Description:** SEC COR 13 14 23 24 63 **Date Set:** **County:** Olmsted

Section: 13 **Township:** 106N **Range:** 13W **Monument Description:**

Reference Ties:

The corner falls in centerline of CSAH 19 north and 2' south of centerline of CSAH 23 east
County highway disk in 18" Oak W 85.5'
Ref pipe SE 123.39'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, William Jones; 80.0 set section post at corner to section 13-14-23-24. RPs- 7" burr oak N87 1/2 E228, 13" burr oak N42 1/2 W59, 6" burr oak S12 W251, burr oak S62 E182.

6-1877 T. Hunter Pg.318 No.312; Used corner to test corner. Found bearing trees and reset corner with oak stake well down and stones on both sides.

4-1884 T. Hunter Pg.387 No.378; Found stone Pg.318. Meas east, 1/16 in creek and set stake, 16 south set stake, 16 center NW 1/4 24 set stake.

5-1884 T. Hunter Pg.389 No.380; Found stake and stone Pg.380.

6-1898 W.Fraser Pg.631 No.571; Found stone Pg.389, set risers. 16 west set stake and 1/16 corners north.

6-1901 Robert Fraser, Pg.706, No.620 S24; Found stake & stone, Pg.707 No.621 S13; found corner Pg.706, 16 north set stake.

1935 Bk.87 Pg.71 county highway department; Found wood stake. Set 3x10x30 limestone with 1/2" rod on east side and cut cross in stone. RPs- corner fence post west 37.5, 30" oak SW 76.0, 12" oak SE 85.0.

3-1941 county highway department Bk.131 Pg.6; Found stone monument and 1/2" iron pipe. RP- disc in 18: oak west 85.5'.

9-1954 J. Kerr, Bk.60 Pg.18; Found corner. Set 1 1/4" pipe. Run line north2619.27 and found oak stake.

8-14-1969 J. Kerr set short CIM over 1 1/4" pipe. RPs- disc in 18" oak W 85.5, iron stake N 2.5' fence, south side twp road E 174.5. Cut 3/4" pipe off and replaced 1 1/4" pipe in hole 12" down. Sealed CIM even with surface.

11-1969 J. Kerr, run line west and set short iron on bed rock as boundary of west 60 acres 648.44 from CIM. Set 1/2" pipe up 3" near fence north at 10'. RP- 40D in 16" burr oak 30 ± south of fence east at 48.8.

6-1995 County Surveyor found CIM in good condition in intersection of CR 19 and CR 23. Used corner in alignment referenceing before cold recycling bituminous surface of CR 23.

5-30-1997 County Surveyor found CIM down 0.3' in good condition.

5-31-2000 County Surveyor found CIM down 0.3' in good condition. Set ref pipe and tied out corner.

7-19-2002 County Surveyor found CIM down 0.6' in good condition. Removed CIM and found 1" O.D. pipe down 1.4' in good condition. Set 1" square pipe w/cap at surface over 1" O.D. pipe.

8-31-2011 County Survey Crew found 1" square pipe with cap eroded. Set new cap #42638.

5-31-2017 County Survey Crew found 1" square pipe w/cap at surface in good condition and removed prior to 2017 mill and bituminous overlay. Found 1" O.D. pipe down 1.3' in good condition. Left in place.