Certificate of Location of Government Corner

ID#: 631506 **Description:** 1/4 SEC COR 15 16 63 **Date Set:** 11/16/1994 **County:** Olmsted

Section: 15 **Township:** 106N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The monument is down 0.7'
The corner falls 1/2' west of centerline of CSAH 11 and 1' south of PP line west
1/2" iron in fence line west W 200'
1/2" iron in fence line west W 100'
Spike in W side PP NNW 177.6'
Ref pipe W 57.86'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, William Jones; 40.0 set section post at 1/4 section corner. RPs- 8" burr oak S5 E391, 9" burr oak S10 W289.

5-1874 Hunter Pg.243 No.244; found rotted remains of stake. Set new marked stake. 16 west set stone.

9-1951 J.Kerr Bk.52 Pg.60; limestone found in line fence west. Placed limestone pieces around it with 1" pipe on south side.

8-1960 J.Kerr Limestone found. 1" pipe riser; CIM set then removed to grade. Reset by county highway department short pipe set as riser in blacktop level with road surface. 1/2" rod on transit line under fence west at 100' and 200'. RP spike in pp NNW 177.6'.

10-1962 County Highway Department (Bk.281) spike & disc in pp SW 117.49', spike & disc in corner post east 59.96', top of 3rd steel fence post SE 72.24', spike & disc in corner post west 61.65'

5-4-1989 County Surveyor found CIM down .4' in centerline CR 11.

6-22-1994 County highway crew found CIM. Set reference pipe, 1" square pipe w/cap W side CR 11 4' east of N-S pole line & 5' north of E-W pole line.

11-16-1994 County highway crew set 1" square pipe w/cap at surface.

2-13-2004 County survey crew found 1" square pipe w/eroded cap at surface in good condition.

7-12-2005 County survey crew found 1" square pipe w/cap at surface in good condition.

3-7-2012 County survey crew found 1" square pipe with cap at the surface in good condition. Lowered pipe and cap in preparation for bituminous road overlay.