Certificate of Location of Government Corner

ID#: 632006 **Description:** 1/4 SEC COR 19 20 63 **Date Set:** 5/25/2004 **County:** Olmsted

Section: 20 **Township:** 106N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' west of fence south, in line with fence west and 5' north of CP to fences south and west
County Survey Disk in E side 18" Ash N 69.50'
County Survey Disk in N side CP WSW 24.37'
Minnesota Highway Disk in W side CP SSE 4.79'
Sign on CP 5' south
This corner is located by GPS reference stations "Rescue A & B"

Corner History:

10-1853 Gov't Notes; William A. Jones, Deputy Surveyor; North between sections 19 & 20. 40.00 chains set post at quarter section corner and deposited charcoal, made mound, trench, pits, and planted cherry seeds NE & SW.

No subsequent survey records on this corner. After resurvey measurements on this section line and a study of the immediate area of the corner, the County Surveyor decided that the best location for this quarter corner would be to place it on the North- South section line and in line with a fence running west and which fence line is a boundary line between two properties. The lost position of the corner would place it 4.35' north of this accepted position.

9-1971 County Surveyor found rod in center old road cut, long abandoned road. RP- 52 ± due west to center MN State bench mark set in 1970 # 5507S. Rod is 6.28' west of straight line between section corners as computed by MHD. See print of section corner coordinates. Then later moved to point on line & in line fence west.

9-18-1972 County Surveyor reset corner by setting it on N-S section line & in line of fence west. C.I.M. set by MHD crew. RPs- Fence line running N-S 4.83' east, nail & disc in corner fence post 4.83' east, nail & disc in fence post NNE 15.28', copper nail disc in 6" boxelder 25.31' west.

5-19-2004 County Surveyor found monument had been dug out and reset upside down.

5-25-2004 County Surveyor set cast iron cap on telspar pipe at computed location from previous surveys.

8-13-2007 County Surveyor found cast iron cap on telspar pipe down 0.3' in good condition.