Certificate of Location of Government Corner

ID#: 632104 **Description:** 1/4 SEC COR 21 28 63 **Date Set:** 4/30/1969 **County:** Olmsted

Section: 21 **Township:** 106N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 1' SW of line of R/W fence NW
1/2" pipe under fence ENE 50'
1/2" pipe under fence S 50'
Bolt (up 6") in R/W sign post ESE 1.54'
County Survey Disk in SW side CP in R/W fence NW 6.25'
Post w/sign 1 1/2' ESE
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, William Jones; 39.89 1/2 set post at 1/4 section corner. RPs- 8" burr oak N53 E178, 5" burr oak S38 W140.

5-1872 T. Hunter Pg.198 No.208; Corner gone. NEBT standing, apoint avered by Mr. Phil Cavanaugh exactly where original corner stood. Corner came within 1 link of BT distance and within 2 links of midway, set 1/4 post at that point.

1941 A. Armstrong, fence corner has been inplace at least 60 years.

? 5/8" rod in place, long used by surveyors and state highway as corner- set by Mcghie ? MHD.

4-30-1969 J. Kerr set CIM over 1x14 galv. Pipe with 10" square limestone on W & N sides with many stones at bottom & sides. Corner just east of deep erosion gulley in line main fence south. 5' south fence east which is very crooked. RPs- MHD disc in white fence post at bottom SE 2.9', MHD disc in fence post south side 5' N of E 26.4', MHD disc in fence post south 26, 1/2" pipe under fence south 50' up 1", 1/2" pipe under fence 5' N of E 50'. Set pipe as property corner east 566.3' as SW corner 10 acre tract.

9-1980 County Surveyor found CIM with piece of limestone standing on the NW and SW sides. RPs; Bolt (6") in R/W/ sign post with survey marker sign ESE 1.54', CSD in SW side corner post in R/W fence NW 5.99', The monument is approx. 1.2' Swly of the line of the R/W fence running Nwly.

6-8-1989 County Surveyor found CIM in good condition. Used in City of Rochester mapping project survey.

8-4-2005 County Surveyor found CIM in good condition down 0.1'. All M.H.D. are gone, did not look for pipe's but did find bolt & CSD, did not check ties.