Certificate of Location of Government Corner

ID#: 632404 **Description:** 1/4 SEC COR 24 25 63 **Date Set:** 10/2/2006 **County:** Olmsted

Section: 24 **Township:** 106N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 2' south of centerline of CR 123 and 29' west of centerline of field entrance south
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, William Jones; 39.92 set post at 1/4 section corner. RPs- 8" burr oak N61 E313, 8" burr oak S32 W54.

6-1877 T. Hunter Pg.318 No.312; Corner gone, found stump of SW BT with marks plain. Reset corner with stone 6x7x15.

6-1901 R.Fraser Pg.706 No.620; Found stone in center of road in line fence running south.

9-1940 county highway department Bk.131 Pg.2; Found limestone.

7-12-1965 J. Kerr set CIM over stone. RPs- disc in pp S 28.88', disc in pp WNW 97.7', lines fence south and centerline road.

11-1974 County Surveyor used corner in measure east.

7-29-1993 county highway department tied out corner for road construction.

3-24-1994 county highway department set 5/8" rerod.

9-28-2006 County Surveyor found 5/8" rerod down 0.3' in good condition.

10-2-2006 County Surveyor removed 5/8" rerod and set 2' telspar pipe w/cast iron cap down 0.4' driven to refusal.