Certificate of Location of Government Corner

ID#: 632604 **Description:** 1/4 SEC COR 26 35 63 **Date Set:** 10/30/1963 **County:** Olmsted

Section: 26 **Township:** 106N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 25' south of centerline of township road west and 11' east of centerline of township road south
Center 31" Burr Oak NW 47'
Center 10" square telephone box WNW 98'
Center 23" Burr Oak WNW 96'
This corner is located by GPS reference stations "O'Neill F & G"

Corner History:

1853 Gov't Notes, William Jones; 39.98 set post @ 1/4 corner. RPS- 11" burr oak S31°W 74 links, 9" burr oak N9°W 42 1/2.

4-1892 T. Fraser Pg.475 No.454; Meas. From above corner east to NE 36 to set temp point from which to set center 36, no desc. Of corner. Total 7910.6 as north side 36 80.03 gave the line north side S36 leaving east above corner. Corner then in olace likely similar to E 1/4 35 a stone placed when marion originally laid out. Bk.8 Pg.13; Stake set from SW bearing tree.

4-1929 J. Kerr Corner set in this survey, corner now used. Corner of Pg.475 not described likely several feet further west.

11-1961 MHD found 1 1/2" pipe with RR spike on top of stone found by Kerr & farmer. RPs- State reference point 14" oak NW 46.9', State reference point in corner post 31.4'.

10-30-1963 J.Kerr found Irons and Hay Knife. Set CIM over 2 1/2"x17" pipe. RPs- center 22" burr oak NW 47.4', corner fence post NE 31.4', disc tele pole W 74.7', old hay knife blade driven in N-S fence E 25.15'.

10-1983 County Surveyor found Kerr's CIM about 1' SE of mailbox post and about 8" deep. Checked ties; center of 30" burr oak tree NW 47.4' ok., corner post NE now 30.6', center of 10" sq tele box WNW 97.5', center of 18" burr oak tree WNW 95.7', tele pole west is now gone. The 30" burr oak tree NW could be the original NW BT(N9°W 42 1/2 lks). F this is the original tree then Kerr's 1929 corner is not correct and should be about 20' west and 15' north to be at the BT position. Since this corner position has been used at Kerr's 1929 location it probably should be kept where it is until we can dig to try to find corner referred to by Tom Fraser in 1892.

5-5-2006 County Surveyor found CIM down 0.7' in good condition.

11-3-2008 County Surveyor found CIM down 0.7' in good condition.