Certificate of Location of Government Corner

ID#: 632606 **Description:** 1/4 SEC COR 26 27 63 **Date Set:** 8/15/2005 **County:** Olmsted

Section: 26 **Township:** 106N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' west of centerline of CR 123
County Survey Disk in PP #42426 SW 51.19'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, William Jones; 40.0 set section post at quarter corner. RPs- 6" burr oak N46 E 4 1/2, 6" burr oak N45 W6.

6-1892 T.Fraser Pg.492 No.466; Couldn't find any trace of corner in road. Bearing trees gone. Set temp point midway and on line between section corner.

5-1940 J. Kerr Bk.20 Pg.33; Run & meas line below, 26 -27 5261.74. Set point midway 2630.87 and corner at 3946.26 for line west.

6-1951 J.Kerr Bk.51 Pg.68; Run N-S line as in Bk.20. Found W 1/4 26. Set 3/4" iron bat. 16 north set 1/2" iron, 16 south set corner, 16 center NW 1/4 set bridge bolt, 16 center SW 1/4 set.

5-29-1962 J.Kerr placed CIM over rod inplace. RPs- spike in pp WNW 30.0', spike in tele pole NNE 67.5', State reference point fence post SE 46.41', corner lies in center of road.

8-12-2005 County Surveyor found 1/2" pipe down 0.8' bent. Removed pipe and found CIM down 1.8' in good condition.

8-15-2005 County Surveyor removed CIM and found 1/2" rerod down 3.5' in good condition. Removed 1/2" rerod and set 5' telspar pipe with Cast Iron Cap down 0.4'.