# Certificate of Location of Government Corner

**ID#:** 632706 **Description:** 1/4 SEC COR 27 28 63 **Date Set:** 10/23/2000 **County:** Olmsted

**Section:** 27 **Township:** 106N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

**Reference Ties:**

The corner falls in centerline of CR 111 and 212 1/2' north of centerline of CR 101 west
Westerly of 2 CIM R/W monuments E 75.03'
R/W CIM E 25.05'
Punch mark in N end 18" CMP NW 53.56'
Punch mark in S end 18" CMP SW 49.45'
Ref pipe SW 138.99'
This corner is located by GPS measurement

**Corner History:**

1853 Gov't Notes, William Jones; 40.0 set section post at 1/4 section corner and made trench. RP- 12" burr oak N12 1/2 E288.

5-1872 T.Hunter Pg.198 No.208; Corner gone. Reset with boulder stone by witness trees standing. 16 south set stake.

6-1892 T.Fraser Pg.492 No.466; Found boulder. 16 north set stone.

1930 J.Kerr Bk.3 Pg.35; boulder found.

11-1932 county highway department Bk#71 Pg.3; Found boulder stone & stake. Ties- corner fence post SW 43.1, boxelder NW 43.0.

7-28-1966 J. Kerr set CIM over car axle with gear, original boulder just east of shaft. RP- 120D riser, limestone pieces E & S sides.

6-24-1970 County Surveyor removed C.I.M. set 1/2" iron rod.

4-18-1972 County Surveyor reset C.I.M. in blacktop. RP's: Westerly of 2 C.I.M. R/W Monuments E 75.03 another C.I.M. R/W Monument East 25.05 Punch mark in flare clamp lug on N end 18" CMP NW 53.56. Punch mark in flare clamp lug on S end 18" CMP SW 49.45.

5-22-2000 County Surveyor found CIM down 0.2' in good condition. Set ref pipe and tied out corner.

10-23-2000 County Surveyor set 1" square pipe w/cap at surface from 2000 tie out.

8-16-2005 County Surveyor found 1" square pipe with eroded cap at surface in good condition. Replaced cap down 0.1'.