Certificate of Location of Government Corner

ID#: 632805 **Description:** SEC COR 28 29 32 33 63 **Date Set:** 7/2/1981 **County:** Olmsted

Section: 28 **Township:** 106N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 1' south of E-W fence, 3' west of N-S fence and 2' SW of CP to fences N-S-E-W
County Survey Disk in N side Box Elder clump NE 19.85'
Post with sign 1' east
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes: William A. Jones, Deputy Surveyor. North between sections 32 & 33. 80.00 chs. Set post at corner to sections 28-29-32-33. Deposited charcoal and planted cherry seeds NE,SW,SE, & NW. Made mound, and trench with pits.

6-8-1877 Thomas Hunter, Co. Surveyor, (Bk A, Pg 316, No. 310, Old Fieldbook 4, pgs 174-175, and Old fieldbook 5, pg 14) "Section corner missing but Mr. J. Cavanaugh avers that the fence post at this corner of his field was set in the mound where the original corner stood, and that when said fence was taken up he put a boulder stone in the hole where the fence post stood to preserve the corner. On digging we found the said stone as described and also under the stone we found the old post hole with oak bark around the sides of it. We set a new white oak post in the place of the stone and marked it on two sides 1/4 S, under a misapprehension at the moment that it was a 1/4 post instead of a section corner." He used this corner to set the 1/16 East, a stake midway (20.03 1/4 chs) and on line to 1/4 corner 28-33. His filedbook shows a measure south of 40.0 chs to 1/4 corner 32-33 and deflection of 40 minutes west at the 1/4 corner when running south.

6-30-1883 Hunter (Bk A, Pg 385, No. 376 and Old Fieldbook 14, Pg 9) "found corner post of fence markes as described in Survey No. 310." He used this corner to set the 1/16 south, a stake midway (20.00 chns.) and on line to 1/4 corner 32-33.

1930 John Kerr, County Surveyor, (Kerr Bk 3, Pg 35-39) used corner (no description). Measured East to the NE corner 34.

1952 J.Kerr (Kerr Bk 55, Pg 16-17) shows "F corner" here. Measured 2641.87 south to 1/4 corner 32-33 and 5283.75 to south section corner 32-33.

9-2-1980 County Surveyor doubled the line and measure from 1/4 corner 28-33 (found 8-28-1980) over the 1/16 West (stake found). Point came appx. 7.0' west and 1.5' south of the traverse point set on the east side of the corner post of fences East, West, North, and South. Dug from this point East to the corner post but didn't find anything.

9-10-1980 County Surveyor dug at the 1/16 South, but didn't find anything.

7-2-1981 County Surveyor set a C.I.M. over an iron rod as the corner. Set this corner on the line from 1/4 corner 28-33 over the 1/16 west.

6-29-1989 County Surveyor found CIM in good condition 1.8' SW of CP to fences N-S-W.

8-17-2005 County Surveyor found CIM at surface in good condition.