Certificate of Location of Government Corner

ID#: 632904 **Description:** 1/4 SEC COR 29 32 63 **Date Set:** 7/26/1977 **County:** Olmsted

Section: 29 **Township:** 106N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls under N-S fence and in line with fence east
Sign on CP 1/2' north
This corner is located by GPS reference stations "Herefords A & B"

Corner History:

10-1853 Gov't Notes: William A. Jones, Deputy Surveyor; West on true line between sections 29 & 32.
40.10 chs set post at quarter section corner, deposited charcoal, made mound, trench, abd pits. planted cherry seeds NE and SW. 80.20 chains to section corner.

5-25-1859 Thomas Hunter, County Surveyor, (Bk A, Pg 60 No 86) possibly used this corner to set the center of section 29 and the 1/16 North midway (20 chs) and on line.

6-30-1883 T.Hunter (Bk A Pg 385 No 376 and Old Fieldbook 14, Pg 9) "1/4 post missing, but found on digging where the measurement from 3 (Center 32) to B (N1/4 Cor 32) would place it, the remains of old fence post, very rotten, about where the fences running E & W, and N & S cross, and at which point Mr. W. Levan avers the original 1/4 post stood. Set stone on top of the remains of said old post." He used this corner to set the 1/16 south, a stake midway (20.01 chs) and on line to a stake set on the E-W 1/4 line and in the center of the N-S road at the Center 32. The S 1/4 cor. 32 was missing.

8-1961 John Kerr, County Surveyor, (Kerr Bk 84 Pg 12) used fence corner as corner to set the center 32.

8-18-1976 County Surveyor dug around the corner posts to fences N-S-E-W but didn't find anything.

7-26-1977 County Surveyor set a telespar pipe with a C.I.C. as the corner between two corner fence posts. Measured 2640.27' South to the Center 32.

10-10-2006 County Surveyor found cast iron cap on telspar pipe up 0.5' in good condition.