Certificate of Location of Government Corner

ID#: 632906 **Description:** 1/4 SEC COR 29 30 63 **Date Set:** 5/19/1987 **County:** Olmsted

Section: 29 **Township:** 106N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 21 1/2' SE of centerline of CR 101 on curve, 2' east of line of centerline of CSAH 1 south and in line with fence east
Bottle cap in PP #17687 NW 44.21'
County Survey Disk in S side CP ESE 24.64'

Corner History:

1853 Gov't Notes, William Jones; 40.0 set post to 1/4 section corner. Deposited charcoal, made mound, trench, pits, & planted cherry seeds NE & SW.

1957 McGhie Co. set a 5/8" rod. RPs- spike in corner fence post E 29.1, spike in tele pole SE 43.6, spike in tele pole NW 41.55.

9-7-1971 County Surveyor found a 5/8" rod set by McGhie. Set CIM over rod. Corner accepted until proven otherwise as no records of orginal corner known. RPs- 29.1 E to line of east road fence running north, 43.67 SE to spike tele pole #9880, 41.45 NW to 7up cap in PP #17687, 131.0 SW to pepsi cap in pp# 17686.

5-19-1987 County Surveyor found stake hole, set telspar pipe/C.I.C. 1' north of fence running east on curve from N to SW. RPs- Pop can in S side corner post EDE 24.64, cic/p 1.23 N & 4.18 E of old CIM location.

2-27-2004 County Surveyor found cast iron cap on telspar pipe down 0.2' in good condition.

10-10-2006 County Surveyor found cast iron cap on telspar pipe down 0.2' in good condition.