Certificate of Location of Government Corner

ID#: 633006 **Description:** W 1/4 SEC COR 30 63 **Date Set:** 2/27/2004 **County:** Olmsted

Section: 30 **Township:** 106N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 4' south of centerline of CR 101 and 20' west of centerline of driveway south for flood control pond
1" pipe under fence north N 32.57'
Spike in PP #18126 NW 56.72'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, William Jones; 40.0 set post and drove stake for quarter section corner. Built mound with trench, and planted SE osage orange seeds & NE apple seeds.

7-1857 T.Hunter Pg.35 No.56; Used corner. Set 16 east,west,south, center SE 1/4 25,16 center SW 1/4 30.

11-26-1963 J.Kerr set CIM over 1 1/2" pipe. RPs- center 2" pipe rail S end culv. W 167.45', 1" pipe under fence N 32.6', spike pp NW 55.54'.

6-1990 County Surveyor found CIM ± 4' south of 3/4" iron found in 1989.

8-16-2001 Mn/DOT survey crew found CIM in good condition and took additional reference ties.

2-26-2004 County Surveyor found CIM with head broken off down 1.3' in good condition.

2-27-2004 County Surveyor found CIM down 1.3' with head broken, took local ties and removed. Found 1 1/2" iron pipe down 3.0', took local ties and removed. Ties matched N-S but were off by 0.04 E-W. Set 6' telspar pipe w/CIC from local ties taken from pipe down 0.45'. Spike in power pole #18126 56.72' NW and 1" pipe 32.57' north. Fence gone, did not check ties to culvert west.

11-14-2006 County Surveyor found p2 w/CIC down 0.45' in good condition.