Certificate of Location of Government Corner

ID#: 633105 **Description:** SW SEC COR 31 63 **Date Set:** 7/27/1964 **County:** Olmsted

Section: 31 **Township:** 106N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls in NW'ly road ditch
County Survey Disk in PP #193 NE 66.08'
Spud in top 10" creosoted post NW 20.1'
County highway disk in PP #9339 SE 71.36'
County highway disk in W side TP SW 75.95'
This corner is located by GPS measurement

Corner History:

6-1863 P.C. Compton Pg. 72 No.104 shows section corner used to set 1/16 north M & L(No measu.)

1875 State law required that monuments be set at township corners. Thomas Hunter, County Surveyor, placed stone monuments as required although there is no survey notes documenting this particular corner

6-1892 W. Fraser Pg.502 No.472; Found engraved twp monument. South set stake 9.81 then 21.305, then 8.75 to W 1/4 6 quarry stione set M &L.

4-1917 County highway department Bk.18 Pg.26 found twp corner stone.

9-1933 J. Kerr Bk.9 Pg.5; Found stone, meas. South 2634.8 to stone found. RPs- W 1/4 6. Run line north to 1/16 corner post avered by John Cochran as corner post set in survey when he was present 2634.32.

1962 county highway department found engraved limestone. RP- old tie spike in 10" twin oak NNW 28.1

7-1964 J. Kerr set CIM over engraved monument. RPs-The corner lies about 10' W. of a channel iron sign post in the median of Co. road # 9. 1 1/4" pipe east 36.0, CSD above spud in pp #193 NE 66.08, spud in top 10" creosoled post NW 20.1, Disc in pp #9339 SE 71.36, Old ite spike in 10" twin oak NNW 28.1, Top RR tie corner post SE 88.02, Telephone pole (disconnect side) SW 75.95.

1974 County Surveyor found CIM in Nwly road ditch. Offset to north and ran line west. Found N 1/4 1 HF Twp.

3-9-2004 County Surveyor found CIM in good condition.