# Certificate of Location of Government Corner

**ID#:** 633106 **Description:** W 1/4 SEC COR 31 63 **Date Set:** 8/3/1977 **County:** Olmsted

**Section:** 31 **Township:** 106N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

**Reference Ties:**

The corner falls 7' south of centerline of ditch and 23' east of rough N-S fence line
Spike in 10" Burr Oak NE 44.7' (slope)
County highway disk in 13" Burr Oak WNW 11.78'
County highway disk in 10" Burr Oak NW 14.91'
Post w/sign 1 1/2' south
This corner is located by GPS reference stations "Scout B & C"

**Corner History:**

1853 Gov't Notes, John Ball, Deputy Surveyor North between 31 and 36. 40.00 chs. Set post and drove charred stake. Built mound with trench and planted Osage Orange S.E. and Apple seed N.E.

7-1857 Thomas Hunter (P. 35 No. 56), County Surveyor, used the corner to set the 1/16th North midway and on line and measured 38.92 chs. (2568.72') to the center 31.

6-1863 P.C. Compton Pg. 72 No. 104 shows 1/4 cor. used in sec. 36 breakdown.

6-1870 Thomas Hunter (Old Road Survey Field Book Page 102) shows that the old road crossed the E-W 1/4 line of section 31 1.76 chs. East of the W. 1/4 Cor. 31.

9-1933 John Kerr (B. 9 P. 5), County Surveyor, set a 3' long Oak stake with a boulder on the South side and rock piled around on line from the S.W. Cor. Sec. 31 to the corner post at the 1/16th North and at 2625.34' North of the S.W. Cor. 31. Took bearing trees: 8" Bur Oak N.W. 11.0' 10" Bur Oak W. 7.0'.

8-1950 John Kerr (B. 51 P. 3) found the corner set in 1933.

7-1977 County Surveyor found Kerr's bearing trees but his corner was gone. Set a spike from the bearing trees.

8-3-1977 County Surveyor set a Cast Iron Cap on a square pipe as the corner on theline from the E. 1/4 Cor. 31 over the center 31 (a stone found) and at Hunter's measure of 1.76 chs. West from the center of the old road. The corner came 4.74' East and 1.89' South of the location of Kerr's corner.

12-1-1980 County Surveyor set survey marker sign and post 1 1/2' south of C.I.M.

3-1-2004 County Surveyor found telspar w/CIC in good condition up 1.2'. Did not check ties.