Certificate of Location of Government Corner

ID#: 633204 **Description:** S 1/4 SEC COR 32 63 **Date Set:** 10/16/2000 **County:** Olmsted

Section: 32 **Township:** 106N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1' west of centerline of CSAH 1 and in centerline of E-W twp road
County highway disk in CP SE 60.18'
Punch hole in S end CMP SW 38.39'
County Survey Disk in PP #44229 NW 131.26'
County Survey Disk in RR tie CP NE 60.45'
Ref pipe WNW 51.59'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes: John Ball, Deputy Surveyor West between sections 5 and 32. 40.00 chs. Set post and drove charred stake. Built mound with trench and planted Osage Orange S.E. and Apple seed N.E.

5-1952 John Kerr (B. 55 P. 16), County Surveyor, set an iron rod midway and on line between the section corners as the corner. RPs- spike & disc large trans pole NW 49.98, spike & disc in tlel pole NE 51.12, disc corner fence post SW 57.9±, disc corner fence post SE 56.4±.

1960 county highway department (B. 230 P.1) found the remains of a cedar stake with small pieces of limestone standing vertical around it.

7-29-1969 John Kerr set a short C.I.M. in new blacktop from County Highway Department references.

9-31-1969 John Kerr found that the County Highway Department references were not to the corner set in 1952 so ran the South line of section 32 and reset the C.I.M. 7.7' West and 1.4' North at the midway and on line location. RPs- disc in pp NW 43.91, disc in corner post SW 52.3, disc in tele pole NE 57.18, corner lies 8' west center road N-S in line cneter road west.

4-27-1976 County Surveyor dug with backhoe at the County Highway Department rod in the centerline of CR 1. Found the rod over a hub over another hub over a 1" x 2" stake and small pieces of limestone in clean clay. Removed all and set a nail at the road surface.

7-26-1977 County Surveyor set a C.I.M. at the location of the County Highway Department corner 1.67' South and 7.45' East of Kerr's C.I.M. (removed). RPs- old disc in corner post SE 59.29, CSD in PP #44229 NW 131.26, punch hole top south end CMP in road west SW 38.37.

9-1989 County Surveyor found CIM, checked ties, cut off tele pole gone, old disc in corner post SE 60.18, punch hole top south end CMP SW 38.39, CSD in RR tie corner post NE 60.45'.

6-2-2000 County Surveyor found CIM down 0.5' in good condition. Set ref pipe and tied out corner.

10-16-2000 County Surveyor set 1" square pipe w/cap at surface from 2000 tie out.

3-7-2006 County Surveyor found 1" square pipe w/cap at surface in good condition.