Certificate of Location of Government Corner

ID#: 633205 **Description:** S SEC COR 31 32 63 **Date Set:** 6/19/1969 **County:** Olmsted

Section: 32 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 1' south of centerline of E-W twp road and 3' west of centerline of field entrance north
Punched cross in E end 24" CMP NE 32.62'
Orange cap in PP #24999 NW 48.5'
Punched cross in W end 24" NW 34.62'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, William Jones; 80.0 set post & frove charred stake corner to section 5-6-31-32. Built mound with trench and planted osage orange SE and apple seed NE.

6-1892 W. Fraser Pg.502 No.472; Found boulder stone set as corner. 16 south set stone & stake.

5-1917 C. Armstrong Bk.K Pg.19; Stone shown as corner.

1927 county highway department Bk.45 Pg.147; Found stone. RPs- hub NW at corner of fence 40.5, spike in fence post south 35.0.

5-1952 J. Kerr Bk.55 Pg.16; Found boulder stone. Set 1/2" rod at S 1/432.

8-8-1961 J. Kerr found a boulder stone and iron pipe and placed a cast iron monument over pipe. Set 3/4 " pipe under fence south 100.0' RP-spud in pp NW 48.5, Spike in power pole northwest 48.50 feet, 3/4" pipe in fence line south 100.00 feet, + in headwall culvert north of west 290.00 feet.

1962 county highway department; boulder 2 1/2' below surface. RPs- spike & disc in 12" box elder NW 105.3' south side, spike & disc in 10" box elder SW 52.3' NW side, spike & disc in 6" box elder SE 104.1' west side, spike & disc in corner post S 62.1 west side.

7-1965 J.Kerr removed CIM for grading. Set new transit tie, rod NNW and nail in old box elder tree. Set 1/2" rod.

6-19-1969 J.Kerr set CIM. RPs- punched cross in east end 24" galv. Culv. Road north NE 32.62, orange cap in PP #24999-D13-31-1.0-18.0 NW 48.5, punched cross in east end 24" galv. Culv north NW 34.62, 3/4" pipe under fence at 100' still in place.

10-10-2006 County Surveyor found CIM down 0.5' in good condition.