Location of Center of Section

ID#: 633209 **Description:** SEC CEN 32 63 **Date Set:** 10/16/2000 **County:** Olmsted

Section: 32 **Township:** 106N **Range:** 13W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.

1" square pipe w/cap RLS #15809

County Surveyor recommends using the computed intersection of quarter lines for the center of section.

Reference Ties:

The corner falls 8' west of centerline of CSAH 1, in centerline of CR 111 east and in line with fence west
The monument is at the surface
Punch mark in lug north end CMP NW 42.32'
County Survey Disc in power pole #50441 WNW 38.81'
County Survey Disc in stub telephone pole SE 66.28'
Ref pipe SW 33.64'
This corner is located by GPS measurement

Corner History:

10-2-1858 H.W. Farrington, (Old Road Book, Pages 141-142, Road No. 93 and New Road Book, Pages 202-203, Road No. 93), used east-west quarter line for road survey.

6-30-1883 Thomas Hunter, County Surveyor, (Book A, Page 385, Survey No. 376), set temporary stake on east-west quarter line and in center of north-south road. 1/16th North set stake midway and online at 20.01 chains (1320.66').

12-1-1932 County Highway Department, (CHD Book No. 71, Page 10), assumed corner. P.I. Sta. 163+80. RPs - Corner post W 32.5', Telephone pole SE 82.7', Hub NW 54.6'.

1957 County Highway Department, (CHD Book No. 230, Page 2), assumed corner. P.I. Sta. 65+50.05. RPs - Spike in corner post NE 52.7', Spike in power pole NW 44.1'.

8-9-1961 John Kerr, County Surveyor, (Kerr Field Book No. 84, Page 12), set 1/2" rod intersecting quarter lines. RPs - Disc in telephone pole SE 56.05', Disc in power pole NE 64.94', Disc in power pole WNW 35.95', Top center north end CMP SSW 89.5'.

11-15-1961 County Highway Department, (CHD Book No. 230, Page 2), found 1/2" rod. Set Cast Iron Monument. RPs - Spike & Disc in power pole NE 56.18', Spike & Disc in power pole NW 48.69', Spike & Disc in telephone pole 44.60'. Disc in telephone pole/power pole combo NE 64.95', Disc in power pole WNW 35.94'.

7-31-1969 John Kerr, County Surveyor, found Cast Iron Monument down 0.4'. RPs - Disc on SE side telephone pole/power pole combo, up 3.0', NE 64.95', Disc on NE side power pole WNW 35.94', Top center north end CMP SSW 89.5'.

9-27-1974 County Highway Department, (CHD Book No. 386, Page 3), found Cast Iron Monument. P.I. Sta. 0+00.

7-21-1977 County Surveyor found Cast Iron Monument and removed. Dug and found a black mark in clay beneath the oldest road extending 1' down into clay which is possibly Hunter's stake hole. Black mark falls 1.6' south and 4.0' east of Cast Iron Monument.

7-26-1977 County Surveyor, after correcting South 1/4 Corner Section 32, set 3/4"x13" rod at intersecting quarter lines. The 3/4" rod falls 1.47' north of the black mark found and 0.13' south and 4.0' east of the Cast Iron Monument position. The corner falls 8' west of centerline of CSAH 1, in centerline of CR 111 east and in line with fence west. RPs - County Survey Disc in power pole WNW 39.75', Punch mark in lug north end CMP NW 42.32'.

Correction of a Corner: The correct corner is 0.13' south and 4.0' east of Cast Iron Monument (removed).

3-31-1981 County Highway Department, (CHD Book No. 386, Page 3), found 3/4" rod. P.I. moved 3.90' east. P.I. Sta. 0+03.90. RPs - Disc in power pole WNW 39.78', Top center north end CMP SSW 90.27'.

9-5-1989 County Survey Crew found 3/4" rod and took new ties. RPs - County Survey Disc in power pole #50441 WNW 38.81', County Survey Disc in stub telephone pole SE 66.28'. RP to CMP ok.

10-28-1998 Vince Fangman found and used 3/4" rod at intersecting quarter lines.

6-2-2000 County Survey Crew found 3/4" rod down 0.7' in good condition. The corner falls 8' west of centerline of CSAH 1 and in centerline of CR 111 east. Set 1" square pipe w/cap as reference and referenced corner prior to cold recycling bituminous project. Removed 3/4" rod.

10-16-2000 County Survey Crew set 1" square pipe w/cap at surface from references for 2000 bituminous overlay project. The corner falls in 7-1/2' west of centerline of CSAH 1 and in centerline of CR 111 east.

10-10-2006 County Survey Crew found 1" square pipe w/cap at surface in good condition and measured its position using GPS.

3-29-2016 Joel Thoreson, County Surveyor, recommends using the computed intersection of quarter lines for the center of section. Based on the county's section breakdown, the 1" square pipe w/cap, as located by GPS in 2006, falls 0.07' south and 0.38' east of the computed center.