Certificate of Location of Government Corner

ID#: 633405 **Description:** S SEC COR 33 34 63 **Date Set:** 11/7/1969 **County:** Olmsted

Section: 34 **Township:** 106N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls in centerline of E-W twp road and 6' west of fence south
County Survey Disk in E side CP SSE 35.97'
County Survey Disk in E side of east brace post NNE 31.55'
County Survey Disk in S side PP #41507 ENE 136.66'
Punch + in W end 15" CMP SE 50.98'
GPS saturation monument Fogarty SE 52.43'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, William Jones; set post & drove stake corner to section 3-4-33-34. Built mound with trench and planted SE osage orange and NE apple seed.

5-1872 T. Hunter Pg.198 No.205; Found stone in center of road.

6-1877 T. Hunter Pg.316 No.310; Found stone Pg.198 avered by Mr. Twohy that he helped place stone in original mound.

9-1884 T. Hunter Pg.392 No.383; Found stone.

9-2-1965 J. Kerr found large limestone. Set CIM over limestone & plow. Nothing to reference to.

9-1969 J. Kerr; Removed CIM for grading. Set 1/2" rod at exact point of center CIM. Set 1/2" rod north at about 358° AZ to center of most easterly of 3 hanging insulators 1/2 mile north. Set at 50.0' with bed rail on each side in bean field until corner can be reset.

11-7-1969 J. Kerr reset corner after grading. Removed tie from field north. Corner in center new grade. RP-+ in west end 15" field drive culv. SE 50.98'.

2-4-1976 County Surveyor took references to CIM. RPs- CSD East side corner post SSE 35.97', CSD east side of most easterly of pair of brace post NNE 31.55', CSD south side PP #41507 ENE 136.66'.

4-1976 County Surveyor dug and found nothing. Will use Kerr's corner as being correct.

10-31-1996 County Surveyor found CIM in good condition.

8-22-1005 County Surveyor found CIM down 0.6' in good condition.