Certificate of Location of Government Corner

ID#: 633406 **Description:** 1/4 SEC COR 33 34 63 **Date Set:** 8/26/1980 **County:** Olmsted

Section: 34 **Township:** 106N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 15' south of centerline of twp road east, 16' west of centerline of field drive south and in line with short fence north
County Survey Disk in SE side PP #17567 NE 80.48'
1/2" rod under fence SE 57.10'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes: William A. Jones, Deputy Surveyor; North between sections 33 & 34. 40.00 chains set post at quarter section corner in mound of earth,sod, deposited charcoal, and made a trench with pits and planted NE & SW cherry seeds.

10-1858 H.W. Farrington, Surveyor,(Old Road Book;Rd No 93) surveyed the road on the E-W 1/4 line Section 33.

5-9 to 5-11-1872 Thomas Hunter, County Surveyor, (Bk A Pg 198 No 208, Old Fieldbook 1, Pg 15 and Old Fieldbook 2, pg 10) "1/4 post missing, but found remains of old mound and also found blazed line running North from said old mound; no remains of stake to be found by digging. Drove short stake in center of mound." He used this corner to set the 1/16 North midway (19.94 chs) and on line and the Center 33, a temporary stake, at inter-secting 1/4 lines.

6-1876 T.Hunter (Bk A, Pg 297, No. 292 and Old Fieldbook 4, Pg 128) "Nothing to be found at D (1/4 Corner 33-34) as left in Survey No. 208 and described as stake. "He set a 2"x6"x15" stone as 1/4 corner 33-34 at double the line and measure (19.96 1/2 chs) from section corner 27-28-33-34 (as set P.198) over the 1/16 South (as set P. 198). He used this corner to set the Center 34 at intersecting 1/4 lines (Hunter later learned that he didn't have the correct point at 1/4 corner 34-35 when he ran the E-W 1/4 line in section 34.

6-1877 T.Hunter (Bk A, Pg 316, No. 310, Old fieldbook 4, pg 174-175, and Old fieldbook 5, pg 14)"found boulder stone as set by me in Survey No. 292." He used this corner to set the Center 33, a stake at intersecting 1/4 lines and the 1/16 West of the Center 33, a stake midway (19.89 1/2 chs) and on line.

1932 county highway department (county highway department Bk 71 Pg 5)"found sharp pointed limestone about 8" under south shoulder of present road."

6-13-1969 John Kerr, County Surveyor, (Kerr Bk 101, Pg 35 and Cert. Filed) "found stake and stones at 1/4 corner section. Measured north 1317.95 and found limestone 1/16 cor. Set C.I.M. Card" Found stone, stake, nails, easily. Set C.I.M. over 1/2"x2' rod, stone, glass, and trash. RPs- pepsi cap in PP #17567 NE 80.48, coke cap in tele pole SE 37.71, corner lies in line center road N on south edge E-W road.

4-20-1976 County Surveyor dug out Kerr's C.I.M. for road grading. Found 1/2" rod over C.I.M. over pieces of lime-stone and 1/2" rod at road surface. Dug at the 1/16 North and found a 1/2"x2' rod over a 4"x5"/11"x13" limestone with a possible stake hole on its West side. Reset rod over the stone.

4-26-1976 County Surveyor dug at the Center 33 but didn't find anything.

9-20-1976 County Surveyor took additional reference to the 1/2" rod at this corner.

8-26-1980 County Surveyor found rod set 4-20-1976 bent over after road grading. Removed rod and set a Cast Iron Monument over a 5/8" rod from references taken 9-20-1976.

8-22-2005 County Surveyor found CIM down 0.4' in good condition.