Certificate of Location of Government Corner

ID#: 633605 **Description:** S SEC COR 35 36 63 **Date Set:** 8/1/2007 **County:** Olmsted

Section: 36 **Township:** 106N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1' west of centerline of CSAH 19 and 12' south of edge of woods east
This corner is located by GPS reference stations "19 & 141 A & B"

Corner History:

1853 Gov't Notes: John Ball, Deputy Surveyor; 80.0 chs set post to section corner. RPs-10" burr oak S49° W 264 links, 10" burr oak S79°E 274 links.

4-1899 W. Fraser for Marion Village; Found boulder stone 2x12x20 as corner and tested with bearing tree.

1900 R. Fraser Field Bk. Pg.23-26 and Bk.A Pg.653; Found W.C.F. stone. 6.42 2/3 chs north of centerline RR measured east to 1/4 corner. 1 link short (39.99)=2639.34'.

4-1902 Thomas Fraser Pg.475 No.454

1903 Charles Armstrong Bk.B Pg.63 found boulder.

1938 Bk.96 Pg.3; Couldn't find corner. Fell in east ditch of twp road, assumed gone. Set 2" steel shaft 2 1/2' long M & L between S 1/4 36 and S 1/4 36 west to 1/16 fence south 1319.0'. Note: this corner set 8.75' E of one John set 1929.

1940 J. Kerr Bk.20 Pg.63; Set 2" axle shaft. RPs- 6" O SE 93.8, 4" aspen E 99.3, SW blaze on 22" red oak 115.4'.(114.0 S7°45' W in 1929 survey).10-1963

NOTE: Corner lies 416.55' from centerline RR south on section line. Deed to Jack Lands claims center line of Hwy 52 north as 413.4' north of above corner.

10-30-1963 J.Kerr found pipe riser. Set CIM. RPs- center 8" black oak ESE 71.5, 24" blazed oak S8°W 114.4' (gone 1969),, 8" white oak S29°E 89.0' (gone 1969), centerline RR by visual due south ± 416.7.

1968 Olmsted County regraded CR.19 and destroyed the bearing trees making the corner position very doubtful.

6-1969 J. Kerr; all ties gone, but county hub west 67.56'. Run line in from south over 1/16 rod set before grading, checked with hub. Set 3/8x18" rod east of hub with beer cans around hub to help attract needle. RPs- lies 7 1/2' east of rag on barb wire fence, nail in hub on south side 14" burr oak SE 71.56' evidently same tree as 8" black oak mentioned above.

6-1970 County Surveyor found 1/2" rod. Set pipe on tie rod. RP- 14" burr oak 71.56.

7-1-1981 County Surveyor found no sign of Armstrong stone, but did find J. Kerr Iron 647.5 south of the section corner.

5-1982 County Surveyor found 1/2" rod to be set over CIM 9.4' deep. Left CIM in place. RPs- concrete nail N12.55, concrete anil E 8.39.

9-16-2003 County Surveyor did not find monument. Did shoot distance of 2633.29 to determine poximity.

5-2-2007 County Surveyor found concrete nail RP's set in May 1982. Referenced position of ties for 2007 overlays.

8-1-2007 County Surveyor set 1" square pipe w/cap at surface from computed coordinates.