Certificate of Location of Government Corner

ID#: 633609 **Description:** SEC CEN 36 63 **Date Set:** 6/27/1969 **County:** Olmsted

Section: 36 **Township:** 106N **Range:** 13W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.

County Surveyor recommends using the computed intersection of quarter lines for the center of section.

Cast Iron Monument

Reference Ties:

The corner falls 32' east of centerline of north-south township road (75th Ave SE)
The monument is down 1'
Punched cross in north end CMP South 173.5'
Coke bottle cap in west side PP# 15445 NNE 111.3'
Post with sign 2' south
This corner is located by GPS measurement

Corner History:

4-1-1892 Thomas Fraser, County Surveyor, (Book A, Page 475, Survey No. 454) set 7"x7"x18" boulder at intersecting quarter lines. 1/16th South set 6"x6"x20" stone w/cross midway and on line at 19.96-1/8 chains (1317.44') to South 1/4.

6-24-1969 John Kerr, County Surveyor, 1/16th South dug and found 6"x6"x20" stone w/cross down 2' in good condition. Set pipe over stone. RPs - 5/8" rod placed by McGhie as corner of Block 3, 100' from railroad centerline, SE corner of 40' easement strip NW 70.8', Battered pipe in center drive south old garage NNW 107.15', 3/4" head of nail with printing in south side PP #15453 WNW 59.04', Punched cross in SW side 5" steel RR crossing sign SE 24.8'.

6-27-1969 John Kerr, County Surveyor, set Cast Iron Monument over 3/4"x12" rod with glass & junk at base down 1' at intersection of east-west quarter line and line from 1/16th South to 120d spike at North 1/4. The monument falls in center of ditch bottom and 32' east of centerline of north-south township road. RPs - Punched cross in north end culvert South 173.5', Coke bottle cap in west side PP# 15445, NNE 111.3'.

7-27-1977 McGhie & Betts, Inc. found and used Cast Iron Monument.

7-1-1981 County Survey Crew, (1981 Remonumentation Book, Page 55) dug at Cast Iron Monument location and found nothing.

10-18-2004 County Survey Crew found Cast Iron Monument down 1' in good condition and measured its position using GPS. Set post with sign 2' south.

2-8-2005 GGG used computed center at intersecting quarter lines.

8-7-2007 County Survey Crew, 1/16th South found 1/2" pipe down 0.5' in good condition and measured its position using GPS. The corner falls 7' east of centerline of north-south township road (75th Ave SE) and 12-1/2' south of centerline of driveway west. RPs - County Survey Disc in SW side PP #50572 SE 26.59', CSD in NE side PP #50571 WNW 53.62'.

2-25-2011 Joel Thoreson, County Surveyor, recommends using the computed intersection of quarter lines for the center of section. Based on the county's section breakdown, the Cast Iron Monument, as located by GPS in 2004, falls 0.08' north and 0.14' west of the computed center.