Certificate of Location of Government Corner

ID#: 640204 **Description:** 1/4 SEC COR 2 11 64 **Date Set:** 7/7/2003 **County:** Olmsted

Section: 02 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 49' north of centerline of WBL of TH 14, 55' east of centerline of driveway north and 4 1/2' south of south edge of blacktop bike trail
County Survey Disk in PP #06618 ENE 45.19'
Post with sign 2' north
This corner is located by GPS measurement

Corner History:

7-2-1854 Gov't Notes W.B. Yerby, Deputy Surveyor West between sections 2 and 11. 40.075 chs Set a quarter section post. Br. Oak 10 in. N63E 70 lks. Br. Oak 12 in. S7W l00 lks. 80.14 to section corner.

5-26-1932 John Kerr, County Surveyor, (Bk 8, Pg. 2) set concrete monument midway and on line between section corners 2637' both halves.

7-13-1972 County Surveyor found the top of a large square concrete monument. Meas. (elec.) the line W to sec. corner 2-3-10-11 2637.83. Note: This work was done for the City Engineer's Department.

11-10-1988 County Surveyor found concrete monument in good condition. Used City of Rochester mapping project survey.

7-1997 McGhie reports monument broken up.

2-25-2003 County Surveyor found concrete monument down 1.4' in good condition.

7-7-2003 County Surveyor found concrete monument down 1.4'. Removed monument and set 5' telspar pipe with cast iron cap at surface from local ties.

3-1-2010 Ken Manahan, Mn/DOT Crew Chief, found cast iron cap on telspar pipe at surface in good condition.