Certificate of Location of Government Corner

ID#: 640205 **Description:** SEC COR 2 3 10 11 64 **Date Set:** 6/18/1973 **County:** Olmsted

Section: 02 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls on slope for turn lane for Hwy 52 entrance ramp
Center concrete pillar for Highway 52 sign SSE 32'
Center transformer box E 77 1/2'
Post w/sign 2' north
This corner is located by GPS measurement

Corner History:

1854 W.B. Yearby Gov't Notes 40.00 set a section post. RPs-White Elm 10N 21/2 W 42 lks. White Ash 8 S 871/2 E 25 lks.

Corner stone in open field of George Baily for many years. Corner preserved in construction of new concrete roads of TH 52.

7-13-1972 County Surveyor found iron shaft as preserved corner.

6-18-1973 County Surveyor set CIM over 1 1/4" x 30" pipe in place of iron shaft.

11-10-1988 County Surveyor found CIM in good condition. Used in City of Rochester mapping project survey.

1-8-1997 Mn/DOT note from corner maintenance record: This corner was recovered and ties were verified and/or re'established if not in place.

4-19-2002 Mn/DOT survey crew found CIM down 0.7' in good condition.

10-2-2002 County Surveyor found CIM down 0.7' in good condition.

10-30-2002 County Surveyor set post w/sign 2' North.

7-11-2006 County Surveyor found CIM down 1' in good condition.

3-1-2010 Ken Manahan, Mn/DOT Crew Chief, found CIM down 1' in good condition.