Certificate of Location of Government Corner

ID#: 640305 **Description:** SEC COR 3 4 9 10 64 **Date Set:** 12/18/2006 **County:** Olmsted

Section: 03 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in N-S tree line and 18' east of N-S fence
Concrete nail in S side 24" Oak W 3.56'
Post w/sign 2' North
This corner is located by GPS reference stations "Baihly Summit B & C"

Corner History:

1854 Gov. Notes W.B.Yerby 80.00 set section post to sections 3-4-9&10. RPs- Burr Oak 12N 46 W 146 lks. Burr Oak 18N 811/2 E 130 lks. White Oak 12S 171/2 E 80 lks.

7-1857 T. Hunter Pg. 34 No. 55, Shows sec. Corner, 1/16 west 19.77 M&L to 1/4 post, 1/16 south 19.93 M&L to 1/4 post (2 Bearing trees to 1/16 corner).

9-1857 T. Hunter Pg. 37 No. 59 shows section corner, 1/16 east 20.18 chs. Then 10.09 M&L to 1/4 post.

6-1871 Perry P. 212 No. 220 found org. stake, SE bearing tree standing & stumps of NE & NW trees - meas. East 39.94'.

5-1956 An interior corner (no roads) corner found, reset or asumed. Now 2" pipe with 3/4" riser 1' above ground. Lies in tree line 18' east of N-S fence found by McGhie.

1960's J. Kerr - Set 2" pipe & 3/4" pipe.

1-18-1989 County Surveyor found 3/4" pipe inside 2" pipe. Used in City of Rochester mapping project survey.

10-3-2002 County Surveyor found 3/4" inside 2" riser up 1.1' in good condition. Set post w/sign 2' North.

12-18-2006 County Surveyor found 3/4" pipe inside 2" riser. Removed pipe and riser and set 3 1/2' telspar pipe with cast iron cap.