Certificate of Location of Government Corner

ID#: 640405 **Description:** SEC COR 4 5 8 9 64 **Date Set:** 2/15/2002 **County:** Olmsted

Section: 04 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 41' south of centerline of E-W twp road
County Survey Disk in E side PP NNW 7.91'
County Survey Disk in S side 24" Elm NE 51.27'
Post w/sign 2' South
This corner is located by GPS measurement

Corner History:

Gov't Notes 80.00 set post to 4-5-8-9 in mound of earth, deposited charcoal, made trench and pits, and planted osage orange NW & SE of trench.

7-1857 T. Hunter Pg. 34 No. 54 - shows section corner 1/16 south 19.77 M&L. Property corner east 17.50 chains then 16.85 chains to property corner then 5.48 to 1/4 cor.

5-1875 T. Hunter P. 272 No. 270 corner missing Mr. Stoppel avers he set corner fence post in center of mound where stake was. 16 North set stake M&L 19.90.

10-1892 W. Fraser P.495 No.468 Stoppel removed post & placed stone in its place. Found evidence of old post. 16 east set stake M&L 19.95, meas. North 39.811/2.

8-1893 W. Fraser P.527 No.492 found stone (P. 495) 16 west set stake & stone M&L 20.20.

4-1897 W. Fraser P. 606 No. 551 found stone set P. 495, 16 east set stake M&L 19.95.

10-1952 McGhie - Corner now 6"x6" conc. Marked set in Mayo survey by Williams in unrecorded survey. North corner conc. Footing SW 137.2, Top anchor bolt S 43.65, Top anchor bolt SE 65.6.

12-1975 County Surveyor, 6'x6" conc. Monument up 6" in So. Ditch of E-W road. 41' So. Of centerline under E-W road fence.

7-24-1989 County Surveyor found concrete monument in road ditch.

1-28-2002 County Surveyor found concrete monument at surface in good condition. Set post w/sign.

2-15-2002 County Surveyor removed 6"x6"x2.5' concrete monument. Set 5' telspar w/CIC up 0.4'.