Certificate of Location of Government Corner

ID#: 640504 **Description:** 1/4 SEC COR 5 8 64 **Date Set:** 3/1/2002 **County:** Olmsted

Section: 05 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 51 1/2' NE of centerline of residential driveway
County Survey Disk in 34" Red Oak E 9.18'
County Survey Disk in 40" Red Oak NNW 14.80'
Post w/sign 2' east
This corner is located by GPS reference stations "Munn A & B"

Corner History:

1854 Gov't Notes - W.B. Yerby East Random, 40.00 set tem. Sec. Post west between section 5&8 9° 49' E, 39.96 set a section post. RPs-Burr Oak 9 W 621/2 E 32 lks. Aspen 8 S 30 E 12 lks.

7-1857 Hunter Pg. 34 No. 54 show 1/4 post with 2 bearing trees 1/16 west 19.88 M&L and 1/16 south 19.76 M&L.

1-1858 J. Fellows - See survey for SW1/4 Sec. 5 woodlots.

12-1858 T. Hunter Pg. 58 No. 84 Shows 1/4 post meas. North 33.90 chains to property corner then 6.15 1/2 chains to center. Measure west 39.93 chains - total of 4 measure to property corner.

5-1875 T. Hunter, P.272 No.270 found unmarked stake with org. pieces by its side tested by NE bearing tree still standing and stump of SE Bearing tree, 16 north set stake M&L 19.971/2 (1318.35).

8-1893 W. Fraser P. 527 No. 492 found stake P.272 tested NE bearing tree. Set stone 21/2x12x18 as corner. 16 east set stake & stone M&L 20.20.

2-1897 W. Fraser P.605 No.550 found stone P.527. 16 west found stone by Hunter P.34 M&L 19.98, corner now SW corner Bamber Heights Subd.

5-7-1971 County Surveyor - Found concrete monument up 16" +-. Ran & measure line from concrete monument at center 8 north to 1/16 corner. Concrete monument 1308.5 (J. Kerr 1940 (1390.12).

9-21-1989 County Surveyor found concrete monument. Set sign & post 1.0'E.

3-1-2002 County Surveyor removed concrete monument. Set 5' Telspar Pipe w/CIC up 0.4'. Set sign & post 2' East.