Certificate of Location of Government Corner

ID#: 640505 **Description:** SEC COR 5 6 7 8 64 **Date Set:** 12/12/1975 **County:** Olmsted

Section: 05 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 1' east of N-S fence, 1' north of fence west and 1 1/2' NE of CP
County Survey Disk in W side blazed 10" Oak NNE 47.23'
County Survey Disk in W side northwesterly 8" twin Oak E 42.08'
Post w/sign 1' east
This corner is located by GPS reference stations "Puddle A & B"

Corner History:

1854 Gov't. Notes - W.B. Yerby, 80.00 set a section post. RPs-White Oak 12 n 601/2 W44 lks, Cherry 10 n 42 E 61 lks, Burr Oak 18 S 591/2 E 17 lks, White Oak S47 W 13 lks.

8-1856 T. Hunter Pg. 15, No.24, 1/16 west 19.89 chains M&L 3 bearing trees (N 18deg. E 11 1/2 lks.) & (S48deg.W 8 lks.) & (S69deg.E 20 lks.)

1-1858 J. Fellows Pg. 49, No.71 - see survey for SW 1/4 sec. 5.

4-1858 T. Hunter Pg. 1 No. 2, 1/16 north 20.13 chains M&L bearing trees to 1/16 corner, (S 313/4 54 lks.) & (S 68deg. W 63 lks.), measure west 39.78 chains to 1/14 post.

12-1858 T. Hunter Pg. 58 No. 84, Measure east total of 39.93 chains from 4 property splits, measure north 40.26 chains to 1/4 post.

2-1897 W. Fraser P.605, No.550 found remains of old stake stumps of witness trees proving corner correct. Set new stake with stone planted by its side. RP- 16 south set stone and stake M&L 19.781/2, 16 east found stone M&L 19.98 & bearing trees, east drove stake at 6.0 chains then found stake & witness tree 15.50 chains east of NW 8.

1-1898 W. Fraser P.616, No.559 found corner. 16 north found stake set P1, drove new stake & bearing tree - 8" white oak S10deg.E 141/2 lks. M&L 19.97. Set stake M&L 9.98 1/2 between above 1/16 corner & SW5. Corners east found corner P605 15.50 chains east of SW 5 with stake at 5.0 - 5.50 & 5.0 then 24.46 on to S1/4 5. Corner now 11/4" pipe. No Rp's.

11-1969 County Surveyor, Sankstone say 1/16 stone set P.605, a limestone is still in place south of section corners 5-6-7-8.

12-12-1975 County Surveyor found 11/4" x 32" pipe with limestone on(5-6) E&W sides. Removed pipe, set CIM over, 1/2"x18" rod as(7-8) corner with limestone in N&S sides. Corner 1' E of N-S fence and 1' N of fence W. and 1.5' NE of corner post.

12-19-1975 County Surveyor, 1/16 north of 5-6-7-8; Bearing tree taken in 1897 still standing. Found black mark in clay, fit bearing tree, accepted as corner. Set 5/8" x 15" rod. Corner 1' W. of corner post to fence N-S-E and .62 south and believe .1 west. RPs-Nail S. side (choke cherry) tree SE 11.07, Nail E. side Fraser big tree S 9.72.

10-27-1986 County Surveyor found CIM Okay, 1/16 N. found 5/8" rod set 12-19-1975. Also found pipe/plastic cap #6507, 30E and all north. William Fraser bearing tree decade and lying on ground. Rod checked OK to Rp SE 11.07.

2-22-1990 County Surveyor found CIM, Set sign & post 1.0' east.

2-7-2002 County Surveyor found CIM in good condition up 0.2'.