Certificate of Location of Government Corner

ID#: 640506 **Description:** 1/4 SEC COR 5 6 64 **Date Set:** 10/28/86 **County:** Olmsted

Section: 05 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls under E-W fence
Post w/sign 1' W
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes, W.B. Yerby, North random 5&6 40.00 set temp. set. Post south between section 5 & 6 course S15'E 39.75 set a section post. RPs-Aspen 8 n 25 E 13 lks, Aspen 10 n 371/2 W 26 lks.

4-1856 T.Hunter shows 1/4 post, 1/16 east 19.70 chains M&L, 1/16 south 20.13 chains M&L bearing trees to 1/16 corner (S 313/4°E 54 lks.) & (S 68° W 63 lks.)

11-1856 T. Hunter P.19 No.31, 1/16 east 20.061/2 M&L Bearing tree (n 543/4° W 661/2 lks.) (N59°E 901/2 lks.), 1/16 west 19.70, 1/16 north 20.0 then 19.73 to No. 5-6.

1-1858 John Fellows Pg. 49 No. 71 shows 1/4 post, measure south 40 chains (see survey for wood lots in SW1/4 sec. 5).

12-1858 T. Hunter Pg. 58, No. 84 shows 1/4 post, Measure south 40.26 chains to section corner, measure east 40.25 chains with 4 property splits along the way.

1-1898 W. Fraser, P.616, No.559 corner gone. Run line SW 5 over 1/16 corner north and doubled distance which proved just 15.50 chains west of point set by Hunter, drove stake. 1/16 south found stake set by Hunter & bearing tree stumps. Took new bearing tree 8" White Oak S10°E 141/2 lks. M&L 19.97. East, set stakes at 5 chains; 10.50 chains found stake at 15.50 chains east of W1/4 5.

3-1902 W. Fraser P. 36B found stake set a 1/4 corner P.616, 16 west set stake M&L 19.70 (maybe 19.98) 16 center SE1/4 6 set stake M&L19.97 E-W 1/16 line, 16 south found stake P.616.

10-14-1934 Archie Armstrong Field Book P.24, found wood stake 1633.2 west of center section 5 and set other points on line west of center 5.

6-1974 County Surveyor found bent 3/4" pipe lying flat. Traced hole down about 18" and reset same pipe with top down 12" in culv. Field in same hole. Corner now 16' N of fence post & old 8" oak stump leans north still in place.

10-24-1986 County Surveyor set point at double the line & measure of section corner 5-6-7-8 over the 1/16 north point on N. edge of wood post. 1/16 south of 1/4 corner 5-6 found 5/8" rod set 12-19-1975. Found pipe/cap 6507.30 E & .11' N. Checked Rp. SE OK.

10-28-1986 County Surveyor set 4' telspar with CIC as corner at double the line and measure from section corner 5-6-7-8 over the 1/16th north.

8-31-1989 County Surveyor found Cast Iron Cap on telspar pipe in good condition. Used in City of Rochester mapping project survey.

4-23-2001 County Surveyor found cast iron cap on telspar pipe down 0.3' in good condition.

2-8-2002 County Surveyor found cast iron cap on telspar pipe down 0.3' in good condition.

7-19-2006 County Surveyor found cast iron cap on telspar pipe in good condition down 0.2'.