Certificate of Location of Government Corner

ID#: 640604 **Description:** 1/4 SEC COR 6 7 64 **Date Set:** 2/13/2002 **County:** Olmsted

Section: 06 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

County Survey Disk in 6" Elm NW 22.42'
County highway disk in 6" Elm SE 42.63'
County Survey Disk in 15" Oak ENE 15.70'
Post w/sign 2 1/2' West
This corner is located by GPS reference stations "Irvin A & B"

Corner History:

1854 Gov't Notes, W.B. Yearby, West random 6&7, 40.00 set temp. section post east between sec. 6&7 course N89° 53'E. 38.84 Set a section post. RPs-Aspen 9" N28 W26 lks. White Oak 8" S 651/2 W9 lks.

4-1856 Thomas Hunter shows 1/4 post (Pg. 1, No. 2) Measure east 39.78 to sec. Corner, 1/16 west 20 chs. Then 17.50 chs. To section corner, Bearing trees to 1/16 corner (N 143/4° E 37 lks.) & (S 55° E36 lks.), 16 north 20.33 chs. M&L bearing trees to 1/16 corner (N 41/4°E 17 lks.) & (S 71 1/4° W 18 lks.

8-1856 T. Hunter Pg. 15 No. 24, shows 1/4 post, 1/16 east 19.89 chs. M&L 3 bearing tree's (N 18°E 111/2 lks.)
(S 48° W 8 lks.) (S 69° E 20 lks.)

12-1857 T. Hunter,Pg. 40 No. 62 shows 1/4 post, measure west 20 chs. To 1/16 then 17.20 chs. To sec. Corner 1/16 south 19.52 chns. M&L to center section 7.

5-1871 T. Hunter P. 185 No. 196 found stake, tested bearing tree. South found prop. Corner stake at 15.30 (100.98' then 23.94 (1580' to center sect.), Measure east from above prop. Cor. 20.14 (1329.24').

6-1886 T. Hunter P. 413 No. 402, found stake, SW Bearing tree standing & NW Bearing tree stump west property corner from previous unrecorded survey at 12.50 then 24.77 west to section corner. 16 south, this corner and center set P. 185 both gone. Reset by measure 19.62 south of N1/4 7 and 37.72 east from 1/16 on sec. Line west side NW1/4 7. Set stake 12.50 chains west from above 1/16 corner.

3-1902 W. Fraser P. 36, B. found stake, 16 north set stake M&L 20.19.

3-1911 Ch.Larson P.148 B found stake & Bearing tree; twin oak SW 32° 30' 51/2 lks.

12-9-1975 County Surveyor set CIM over 1/2"x 16" rod over stake hole found.

2-13-2002 County Surveyor removed CIM. Placed 5' telspar w/CIC up 0.4' over iron rod.