Certificate of Location of Government Corner

ID#: 640606 **Description:** W 1/4 SEC COR 6 64 **Date Set:** 6/28/1974 **County:** Olmsted

Section: 06 **Township:** 106N **Range:** 14W **Monument Description:** Witness Corner: 1" iron shaft 24.34' east of corner location

Reference Ties:

Witness Corner East:
The corner falls 20' east of edge of creek
The monument is up 0.3'
County Survey Disc in 15" Elm NNW 14.14'
County Survey Disc in 18" Elm ESE 43.61'
1" pipe set by McGhie & Betts (on w. side of creek) W 57.35'
Post w/sign 2' North
This corner is located by GPS reference stations "Skunk A & B"

Corner History:

10-3-1853 John Ball, Deputy Surveyor, measured north 40.00 chains on true line between Sections 1 and 6. Set post. RPs - 18" Burr Oak S88°W 218 links (143.88'), 16" Burr Oak N56°W 143 links (94.38').

4-1-1856 Thomas Hunter, (Book A, Page 1, Survey No. 2), used quarter post.

12-10-1857 Thomas Hunter, (Book A, Page 40, Survey No. 62), used quarter post. 1/16th South set midway and on line at 19.81 chains (1307.46').

2-17-1882 Thomas Hunter, County Surveyor, (Book A, Page 375, Survey No. 366), used quarter post.

3-21-1902 William Fraser, County Surveyor, (Book B, Page 36), found stump of U.S. bearing tree and located temporary stake.

4-16-1902 Charles Armstrong, (Book B, Pages 34-35), located corner from bearing tree and line of fence east. 1/16th South set oak stake midway and on line at 19.915 chains (1314.39').

4-13-1948 Ken McGhie, corner location falls in creek. Set 1" pipe 33.0' West of actual corner. RPs - Spike in 18" Basswood W 42.4', Spike in 24" Basswood SW 79.6'.

9-6-1961 John Kerr, County Surveyor, (Book C, Page 84), corner falls in creek. Notes 1" pipe 33.0' West of actual corner.

6-28-1974 Roger Brand, County Surveyor, reset this corner at the intersection of the township line between Section 1 106-15 and Section 6 106-14 and the fence line of the east-west quarter line of Section 6 projected west. Set 1"x3' iron shaft as witness corner 24.34' East of actual corner. RPs for Witness Corner - Spike in west side 44" Elm NNE 15.0', Spike in 36" Elm SE 84.7', 1" pipe set by McGhie & Betts (on west side of creek) West 57.35'.

2-14-2002 County Survey Crew found 1" iron rod witness corner up 0.3' in good condition. Old ties had been destroyed. RPs for Witness Corner - County Survey Disc in 15" Elm NNW 14.14', County Survey Disc in 18" Elm ESE 43.61', Post w/sign 2' North. Set GPS reference stations "Skunk A & B" and measured their positions using GPS.