Certificate of Location of Government Corner

ID#: 640704 **Description:** 1/4 SEC COR 7 18 64 **Date Set:** 9/28/1977 **County:** Olmsted

Section: 07 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 2 1/2' south of E-W fence
County Survey Disk in W side 7" Elm N 6.08'
County Survey Disk in N side 11" Cherry W 22.98'
County Survey Disk in E side Burr Oak NW 260.4'
Post w/sign 2' South
This corner is located by GPS reference stations "Donovan A & CR 25 PI"

Corner History:

1854 Gov't Notes, W.B. Yerby, 40.00 temp. sec. Post east between section 7&8 course S89° 48'E. 38.92 set section post in mound, deposited charcoal, made trench & pitts. Planted osage orange seeds N&S.

6-1856 T. Hunter Pg. 9 No. 15, 1/16 west 19.42 chains M&L, Bearing trees (N 331/4°E 661/2 lks.) & (N391/4°W 74 lks.), 1/16 south 20.30 chains M&L Bearing trees (N483/4°W 141/2 lks.) & (S401/4°W 16 lks.)

11-1857 T. Hunter P. 39 No. 61 measure south 39.76 - east 40.20.

3-1858 T. Hunter Pg. 50 No. 73, 1/16 W. 20 chains then 18.55 chains to section corner, Bearing trees (S 81°W 49 lks.) & (S40°E 107 lks.), 1/16 south 19.86 chains M&L to center section, bearing trees (S54°W 51 lks.) & (N51°E 20 lks.)

5-1871 T. Hunter (P.185 No.196) found mound and pits, set new stake.

6-1900 Robert Fraser, P. 704 No. 619, corner is located on section line & porp dist 3' tree N141/4°W 3.94 chains and 12" Burr Oak, Corner now claimed 3/4" pipe.

12-1960 J. Kerr, found concrete monument SE corner 7. Run line west to 1/4 7-18, a 3/4" pipe anchor 2640.95. Set 1/16 M&L 1320.47 a 3/4" steel rod near road N-S. RPs-Punch marks in galv cul NW'ly 17.38, Spike in tele pole NE 32.1. RP S1/47 located on SE side elm stump, N 141/4°W 12" burr oak 260.04'.

9-22-1977 County Surveyor found remains of stake. Stake 2.5' S and 7.1 W of Kerr's pipe and only 3' south of nail set at Fraser's distance.

9-28-1977 County Surveyor set cast iron cap on telspar pipe at stake location. Removed Kerr pipe.

7-25-1989 County Surveyor found telspar (CIC) in good condition.

2-7-2002 County Surveyor found cast iron cap on telspar pipe in good condition at surface. Set sign and post 2' South.