Certificate of Location of Government Corner

ID#: 640705 **Description:** W SEC COR 7 18 64 **Date Set:** 8/6/2007 **County:** Olmsted

Section: 07 **Township:** 106N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CR 104 and 11' south of centerline of twp road west
County Survey Disk in NW side PP #52455 SW 70.74'
1990 Ref. pt (Byron Bank) SSW 214.66'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes - Yerby, 80.00 set post corner section 12-13-7-18. RPs-Black Oak 6 N 60W 13 Black Oak 5 S 75W 10 Black Oak 6 S 88E 93 Black Oak 8 N 67E 59.

12-1857 T. Hunter P. 40 No. 62, Used corner, set 1/16 north M&L 19.81, Bearing tree S59°W 90 lks.

3-1858 T. Hunter Pg. 50 No. 73, 1/16 east 18.55 chains then 20 chains to 1/4 post. Bearing trees to 1/16 east (S 81°W 49 lks.) & (S 40°E 107 lks.), 1/16 south 19.78 chains M&L to 1/4 post.

6-1886 T. Hunter P. 413, No. 402 found stake, set new stake with stones east and west sides.
1/16 north found NW bearing tree P. 40. Stake school house grounds starting 22 chains east of 1/16 corner, then north of 1/16 line 2.5 chains E&W and 2.55 chains N&S.

3-1911 C. Larson P. 148 B 1/16 N. found corner & stake M&L 19.90, 1/16 east found wood stake at 18.871/2 (1245.75)

5-1912 Williams P. 168 B found stone monument. Set corners east from 1/16 corner south, replaced 1/16 east.

1945 Co. Hwy. Dept. (B159P), found stone monument. Measure east to 1/16 corner, stone found 1241.6 R 1245.75 16N iron rod in place.

1953 McGhie - Found pointed boulder. RPs- Spike in pp SW 47.5, sp tele pole NW 51.1, Sp in 12" oak NE 36.55.

10-1968 J. Kerr found stone, set CIM over 5/8" x 7" rod, stone N. side. RPs- 30 D on west side dead red oak NE 36.0, 30 D on SE side pp #8104 WSW 59.75, point of angle corner post at top NW 65.35.

12-1975 1/16E; Dug NE of corner post. Found 2x10x12 + stone 1.35 W and .65 of traverse nail and 1.5' NE of post.

9-21-1977 County Surveyor dug east and north of Kerr's CIM and found two boulders standing side by side. Westerly stone 4x6x9 and easterly
stone 5x10x11. Stones 1 1/2' deep. Drove 5/8"x2' iron between the stones where Hunter records setting stake, but didn't find one. Corner 5.7 north and 4.3 east of Kerr's CIM.

9-23-1977 County Surveyor set CIM over 5/8"x2' iron. RPs- Sp & CSD SW side 11" blazed burr oak NW 127.56 CSD E side pp stub NW 68.62 Sp & CSD W side 15" black oak.NNE 32.60.

5-31-1990 County Surveyor, traverse tie destroyed, set new reference, Bruce Belter set 5/8" iron.

7-2-1993 County Surveyor set 1" square pipe w/cap at surface.

2-11-2002 County Surveyor found 1" square pipe w/cap at surface in good condition.

5-18-2007 County Surveyor found 1" square pipe w/cap at surface in good condition.

8-6-2007 County Surveyor set 1" square pipe w/cap at surface in good condition from 2007 overlay tie out.