Certificate of Location of Government Corner

ID#: 640706 **Description:** W 1/4 SEC COR 7 64 **Date Set:** 8/6/2007 **County:** Olmsted

Section: 07 **Township:** 106N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CR 104 and 20' south of centerline of residential driveway east
County Survey Disk in SW side PP #52445 SSE 130.72'
1989 Ref. pipe (Christenson) SW 195.07'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes - Yerby, 40.00 set post for section corner. RPs-Burr Oak 8 S6 E 323. Black Oak 8 S35 W29.

12-1857 T. Hunter P. 40 No. 62, Used corner to set 1/16 N M&L 19.83. 1/16 west set M&L 19.94. 1/16 south set M&L 19.81 Bearing Tree (S 59°W 90 lks.) measure east 38.06.

3-1911 C. Larson P. 148 B set boulder & stake, 1/16 south found corner M&L 19.90, Measure east 39.3 to center section 7, north found limestone at 19.90 (set by Hunter 1886).

5-9-1961 J. Kerr found iron rod set M&L by McGhie, set CIM over iron rod. RPs-Sp twin oak NE 55.13, Sp tele pole NW 61.8 .

9-20-1977 County Surveyor, at 1/16th south found 6"x8"x16" stone on south side of stake. Removed stake. Corner 2.05N and 3.85 E of McGhie iron (removed). Replaced stake with 2x2 hub and a 1x2 hub and iron bent over stone.

9-20-1977 County Surveyor at Charlie Larson property corner found 11/2" x 20" iron. Set 1/2" x 12" iron @ surface over centerline iron.

9-21-1977 County Surveyor found 10x10x22 boulder with stake on NW side 7' deep. Set angle iron in stake hole. Set a 11/4" pipe on west side of boulder and 5/8" rod on east side. Stake 2.6E and 3.5N of CIM and stone. 3' east of stake.

9-23-1977 County Surveyor set 5/8"x18" rod at stake location.

9-26-1977 County Surveyor set CIM over 5/8" rod at double the line and measure of the 1/16th south 1.8E and 4.3 south of centerline stone and 4.4E & .8' south of Kerr's CIM (removed). RPs- Punch hole top south end CMP in field drive E ESE 32.17, punch hole top n-end CMP in field east ENE 32.97, old disc in NW side twin black oak NE 51.07 corner in center N-S road. T.H. school comes 22 chains east of light. 1/16 n of SW7.

5-3-1989 County Surveyor referenced corner before construction using traverse point. Christenson turned < Rt 1/4 corner 1-12 Salem to W1/4 7 82° 11' 30" for dist. 195.07'.

7-2-1993 County Surveyor set 1" square pipe w/cap as corner in blacktop.

2-11-2002 County Surveyor found 1" square pipe w/cap at surface in good condition.

5-18-2007 County Surveyor found 1" square pipe w/cap at surface in good condition.

8-6-2007 County Surveyor set 1" square pipe w/cap at surface from 2007 overlay tie out.