Certificate of Location of Government Corner

ID#: 640805 **Description:** SEC COR 7 8 17 18 64 **Date Set:** 3/3/2005 **County:** Olmsted

Section: 08 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls on west side of CP to fences north and east (fence's nearly gone)
County Survey Disk in S side 10" Elm E 19.53'
County Survey Disk in E side 20" Box Elder S 48.35'
Post w/sign 1' south
This corner is located by GPS reference stations "CMJ B & Bourquin"

Corner History:

1854 Gov't Notes - W.B Yerby, 80.00 set section corner post. Elm 12N 75 W 18 lks, Elm 10N 861/2 E 17 lks, Ash 8 S 441/2 E 30 lks, ` Ash 14 S 491/2 W 31 lks.

6-1856 T. Hunter Pg. 9, No. 15, 1/16 south 20.09 chains M&L - Bearing trees (n 351/4°E 17 lks.) & (S 693/4°E 23 lks.), 1/16 E 19.42 chains M&L Bearing tree's (N 331/4°E 661/2 lks.) & (N 391/4°W 74 lks.)

11-1857 T. Hunter Pg. 39 No. 61, 1/16 west 20.10 M&L to 1/4 post, 1/16 south 19.92 M&L to 1/4 post.

6-1900 R. Fraser, P. 704 No. 619 found stake avered by Burgoin as true corner. Set new burr oak stake with stone 2x7x15 by its side. Drove iron rod beside stone. 16 west set stake with stone M&L 20.07, came about 15' NW of bridge.

3-1911 C. Larson P. 148 B found wood stake, accepted as section corner SE 7. West shows S1/4 7 at 20.0 entire mile 79.371/2.

12-1960 J. Kerr found concrete mayo marker.

1968 Sankstone found above concrete mayo marker.

12-1975 County Surveyor found concrete mayo monument on w. side corner post to fences N-E.

1981 McGhie & Betts found concrete monument near old fence int.

7-26-1989 County Surveyor found concrete monument next to old post, fence lying on ground. Set sign and post ± 1.0' south.

2-4-2002 County Surveyor found concrete monument leaning.

3-3-2005 County Surveyor removed concrete monument and set 7' telspar w/CIC from computed coordinates up 0.4'. CSD w/conc. nail in south side of 10" Elm east 19.53' and CSD w/conc. nail in east side of 20" Box Elder south 48.35'.