# Certificate of Location of Government Corner

**ID#:** 640809 **Description:** SEC CEN 8 64 **Date Set:** 2/11/2002 **County:** Olmsted

**Section:** 08 **Township:** 106N **Range:** 14W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
Cast Iron Cap on telspar pipe

**Reference Ties:**

The corner falls 32' north of centerline of Valley Ct SW and 37' west of centerline of Westhill Dr SW
County Survey Disk in E side 7" Elm NNW 41.99'
Chiseled X in concrete culvert SE 13.66'
Post w/sign 2' west
This corner is located by GPS measurement

**Corner History:**

7-1-1857 T. Hunter Pg. 34 No. 54, Shows center w 2 Bearing tree's, 1/16 north 19.76 M&L to 1/4 post. 16 west 19.37 M&L to 1/4 post. 1/16 east 19.95 M&L to 1/4 post. Center of NE 1/4 set M&L 19.93 on E-W line.

8-25-1893 W. Fraser P. 527 No. 492 found stake and stone, 16 south set stake M&L 19.771/2. 16 east found 1/16 stake no measure.

1900's? Mayo concrete monument placed by Williams unrecorded survey. Iron rod S 173.7, iron rod W 638.2, Measure north to N1/48 2618.2, Measure west to W1/48 2552.9 (R 1857 38.74) (2556.9).

5-1926 county highway department B. 45, P. 19, Alignment road through Mayowood. Measure east to west RW line N-S Mayowood Rd 1290.6 to centerlines 1323.6.

1945 county highway department Book 160 Center of section 210.5 w. of road, E1/4 966.3' south of road.

5-7-1971 County Surveyor found concrete monument down 2' with steel post by its side.

12-1974 County Surveyor found large boulder over corner section monument - couldn't use at this time.

12-10-1975 County Surveyor removed boulder known to be corner. Dug and found 6"x6" concrete monument. Set 11/4"x4' pipe on E. side (up 11/2'), pieces of fence post around boulder.

12-19-1975 McGhie & Betts found and used concrete monument.

1-11-1984 McGhie & Betts found and used 6"x6" concrete monument.

8-8-1989 County Surveyor found 5/8" pipe/cap #11622 near center.

8-21-1989 County Surveyor found concrete monument with broken top, left down 16" in road ditch.

2-11-2002 County Surveyor found concrete monument w/broken top. Checked with shot taken in 1989 and it checked. Removed monument and set 5' telspar with CIC up 0.3'. Set sign and post 2.0' West.