Certificate of Location of Government Corner

ID#: 640905 **Description:** SEC COR 8 9 16 17 64 **Date Set:** 9/24/63 **County:** Olmsted

Section: 09 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 15' south of centerline of residential driveway
Post w/sign 1' south
This corner is located by GPS reference stations "Mayo Dam & Mayo Lake"

Corner History:

1854 Gov't Notes, W.B. Yerby, 80.00 set section post. RPs-Basswood 12N 271/2 W 22 lks, Aspen 18N 38E 28 lks, Basswood 12S 80E 36 lks. White Oak 12S 873/4 W 39 lks.

12-1893 W. Fraser P. 539 No. 500 found stone as corner in earlier survey, tested by 2 Bearing tree stumps. Measure east 40.13.

5-1926 Co. Hwy. Dept. B.45 - P.25, Cor. Maintained with concrete building block. Found concrete block,also complete align of Mayowood road.

9-1963 J.Kerr - Set CIM with concrete block E. side.

3-7-1977 County Surveyor at 1/16th south found concrete mayo monument lying on ground.

3-14-1977 County Surveyor at 1/16th south reset mayo monu. M&L. Corner on hillside & 63' E of center of N-S ditch.

8-8-1989 County Surveyor found CIM set sign & post 1.0' S, 15.0' north to centerline of driveway.

2-1-2002 County Surveyor found CIM in good condition.

2-7-2002 County Surveyor found CIM up 0.2' in good condition.