Certificate of Location of Government Corner

ID#: 640909 **Description:** SEC CEN 9 64 **Date Set:** 8/8/1985 **County:** Olmsted

Section: 09 **Township:** 106N **Range:** 14W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
5/8" pipe w/cap RLS #11622

Reference Ties:

The corner falls 19 1/2' south of E-W fence, 82 1/2' west of N-S fence and 3' NE of RR tie fence post
Post w/sign 2' north
This corner is located by GPS reference stations "Tall Fence A & B"

Corner History:

7-6-1857 T. Hunter Pg. 34 No. 55, Property corner west 22.75 then 17.50 to 1/4 post, measure east 39.70 to 1/4 post. Measure north 17.74 to property corner then 22.36 to 1/4 post.

1-19-1858 T. Hunter Pg. 47, No. 69, 1/16 east 19.85 chains M&L to 1/4 post.

12-5-1893 W. Fraser, P.539, No. 500 drove stake at inter lines. Cornfleth & Stoppel aver that in spring will set iron rod & plant stone at corner. 16 w came in center river M&L 20.01. Drove stake on 1/4 line at 17.507/8 (1155.6' east of W1/4 9).

10-1939 J. Kerr P.522 B B16, P.43 found concrete monument set in Mayo survey and co. surveyor, 16 east set iron stake M&L 1318.26. RPs-18" black ash center SE 36.5, 10" elm center SW 50.75.

12-1975 County Surveyor found concrete monument in place.

8-4-1976 McGhie & Betts found 6"x6" concrete monument.

4-3-1978 County Surveyor found monument knocked over, set it back up.

2-28-1979 McGhie & Betts reset found 6"x6" concrete monument

7-19-1983 McGhie & Betts found 6"x6" concrete monument.

8-8-1985 McGhie & Betts set 5/8" pipe w/cap #11622 at center of section 9.

8-7-1989 County Surveyor found 5/8" pipe/cap #11622 NE of concrete monument which is leaning. Accepted pipe as corner.

11-8-2007 County Surveyor found 5/8" pipe w/cap RLS #11622 at surface in good condition. Set post w/sign.