Certificate of Location of Government Corner

ID#: 641004 **Description:** 1/4 SEC COR 10 15 64 **Date Set:** 7/1/64 **County:** Olmsted

Section: 10 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 36' west of centerline of Lenwood Drive SW
Spike in W side 24" Oak (up 2.5') NE 11.23'
Pipe property corner NE 28.35'
County highway disk in S side 24" Oak (up 3') NE 10.67'
Steel fence post 1' NW
Post w/sign 2' SE
This corner is located by GPS reference stations "Suk A & B"

Corner History:

1854 Gov't Notes, W.B.Yerby, East Random 10-15 40.00 set temp section post west between section corner 10&15 course 9° 50'E. 40.00 set section post, made trench. Burr Oak 10 S79E 355 lks

6-1871 R. Perry P.212, No.220 found stone monument - Bearing trees gone. Dr. Westfall avers he set stone in place of original stake, 16 west set aspen post in mound of stones 20.0 M&L 16 east set oak post 20.041/2 M&L.

11-1872 T. Hunter P.210 No.218 found stone set by Westfall with original stake beside it. 16 west set oak stake M&L 20.03.

1930 county highway department Book 65 Pg. 32. RPs-Nail in oak NNW 35.6',Nail in oak NW 35.4', Nail in oak WNW 21.3'

1936 Leonard P.460 B found limestone with top broken off, exposed top now 4"x4". 16 east set 5/8" iron pipe M&L 1231.5, Rp. Nail in power pole S40°E 54.3. 16 north set 7/8" drill steel between above 1/16 & 1/4 10-15 331.7 south of 1/16 and 9.95.05 north of 10.15.

1939 J. Kerr Bk. 15 P.107. RPs- Oak trees N'ly 35.6 W'ly 21.3, NW 35.4 , NE'ly 7.0'= center of 6" oak.

7-1964 J. Kerr found stone, set CIM over or near stone.

1-18-1989 County Surveyor found CIM in good condition. Used corner in City Rochester mapping project survey.

4-19-2002 Mn/DOT survey crew found CIM in good condition.

10-1-2002 County Surveyor found CIM up 0.3' in good condition.