Certificate of Location of Government Corner

ID#: 641005 **Description:** SEC COR 9 10 15 16 64 **Date Set:** 8/6/2002 **County:** Olmsted

Section: 10 **Township:** 106N **Range:** 14W **Monument Description:** 5/8" copper plug w/punch mark

Reference Ties:

The corner falls 13.8' east of centerline of NBL of CSAH 8 and 1 1/2' north of centerline CR 125 east
Reference pipe S 72.72'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes, W.B. Yerby, 80.00 set section post to section 9-10-15&16 in mound of earth, deposited charcoal, made trench and pits, and planted osage orange seeds SE & NW.

1-1858 T. Hunter Pg. 47 No. 69, 1/16 north 19.83 chains M&L to 1/4 post, Measure west 39.45 chains to 1/4 post.

6-1871 R. Perry P.212 No. 220, Found stone - 16 corners N&E 20.0 M&L.

11-1872 T. Hunter P.210 No.218. Found stone & stake. Set new burr oak stake by its side in place of old stake. 16 east set stake in pile of stones M&L 20.03.

5-1932 Co. H.D. Book #64, Pg. 42 1/4" iron pipe on west side of stone.

12-1936 J. Kerr - Iron in place. RPs- Oak trees N'ly 35.6 W'ly 21.3. Oak trees NW 35.4 NE'ly 7.0 center of 6" oak.

7-14-1964 J. Kerr set CIM over stones. Corner lies east of road intersections. 1/16 north set rod in old road bed M&L 1313.95.

1-18-1989 County Surveyor found CIM in good condition

7-21-1989 County Surveyor found CIM in good condition

11-18-1989 County Surveyor found CIM in good condition

1-8-1997 Mn/DOT note from corner maintenance record: This corner was recovered and ties were verified and/or re-established if not in place.

1-15-1997 County Surveyor found CIM down 6" in blacktop.

4-19-2002 Mn/DOT survey crew found CIM in good condition.

5-24-2002 County Surveyor tied out corner for CSAH 8 construction. Removed CIM and found 2" pipe down 2.4'. Left pipe in place.

8-6-2002 County Surveyor set 5/8" copper plug w/punch mark at surface in concrete from construction tie out.