Certificate of Location of Government Corner

ID#: 641104 **Description:** 1/4 SEC COR 11 14 64 **Date Set:** 7/18/2003 **County:** Olmsted

Section: 11 **Township:** 106N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1' north of centerline of 20th St SW and 31' east of centerline of 5th Ave SW
Disc in PP S 28.07'
Disc in PP NNE 27.08'
Spike in 16" Oak N 40.7'
60d spike in 24" Boxelder NW 58.37'
This corner is located by GPS measurement

Corner History:

Gov't Notes W. Yerby; 40.00 set temp section post west between 11 & 14 course 9° 04'E, 39.95 set section post. RPs-Bur Oak 12N 1/7 E 210 lks, Aspen 9S 451/2 W 240 lks.

7-6-1855 T. Hunter Field Book #13 P.6&18 show corner used.

4-1875 T. Hunter Field Book #4 P.32-33 found stake standing and set new Burr Oak stake properly marked.

12-1875 T. Hunter, P. 289 No. 285 found stake properly marked. Measure south 40.08 = 2645.28, 16 west M&L 19.921/2 = 1315.05

6-1901 Robert Fraser Pf.703 No.618; Found stake & stones.

1930 CHD Bk# 65 Pg. 30; Iron pipe; Ties-Nail in 12" oak north 40.7, nail in box elder NW 58.4', nail in corner fence post SE 34.9'

4-1939 J Kerr Pg.442B; found stone. Meas. East.

7-18-1963 J. Kerr found limestone with 1/2" iron riser. Set CIM over stone and iron.

3-31-1986 County Surveyor found CIM, head gone, checked reference points; Disc W side PP south 28.07
Disc in E side PP NNE 27.08 Spike in S side box elder, NW 58.37 No spike in oak, PK 10.04 SE of fire hyd. PK transit tie, PK to CIM 66.19 Rt. 137deg. 17' 33" to verticle railing post on top of water tank so. (1st one east of center of tank). Put PK in conc. Curb on W side 5th Ave. SW running south.

7-3-1986 County Surveyor found CIM over 5/8" rod over wagon wheel hub, with stones around & 1"x4"x16" stone on E. side stake 60'E & 1.8' north of CIM.

11-10-1988 County Surveyor found 5/8" pipe, checked ties, good, checked PK nail transit tie. Accepted 5/8" pipe as corner.

6-13-1997 County Surveyor found 5/8" pipe in good condition 1' north centerline 20th St. SW 31' E centerline 5th Ave. SW.

10-1-2002 County Surveyor found 5/8" pipe down 0.5' in good condition.

7-17-2003 County Surveyor found 5/8" pipe down 0.5'. Took local ties and removed. Will replace after blacktop firms up.

7-18-2003 County Surveyor set 1" square pipe w/cap at surface from local ties.

6-16-2009 County Surveyor found 1" square pipe w/cap up 0.1' in good condition. Tapped monument down flush w/surface.

2-26-2010 Ken Manahan, Mn/DOT Crew Chief, found 1" square pipe w/cap at surface in good condition.