Certificate of Location of Government Corner

ID#: 641106 **Description:** 1/4 SEC COR 10 11 64 **Date Set:** 5/14/2002 **County:** Olmsted

Section: 11 **Township:** 106N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls on edge of Rip Rap on Westerly bank of Zumbro River
Post w/sign 2' NW
This corner is located by GPS measurement

Corner History:

7-2-1854 Gov't Notes W.B. Yerby, Deputy Surveyor North between sections 10 and 11. 40.00 chs. Set a quarter section post. White Elm 10 in. N2 1/2W 42 lks. White Ash 8 in. S87 1/2E 25 lks. 41.75 chs. Stream 75 lks wide runs N.W.

6-1871 R. Perry (No. 220 Pg. 212) Found the Elm B. tree standing and the stump of the Ash B. tree. Set an oak stake as the corner. Measured West M & L 19.97 (1317') Measured South M & L 19.90 (1313.4')

1927 Charles Armstrong (Book G (p. 48-55) 1/4 corner - Stone 19" x 12" x 4" Measured South 2621' Measured North 2611' with 1/16 stone set M & L 1305.5' Measured West 2636' (1322' then 1314') 1/16 apparently not midway. Center of NE 1/4 set by crossing 1/16 lines - set stone 22" x 12" x 6" with point on top.

1936 A. Leonard (Bk B. pg 460) Found the long limestone with a 2" x 8" top. The stone was 5 1/2' S and 1 1/2' W of the twin ash used as the corner fences. Measured West 2637.7' Measured South 2641.0'

1940 Archie Armstrong, CHD (Bk 103 pg 61) Found the limestone set a better stone with a drill hole in top 5 x 6 x 22. Measured East 2634.0 to the corner in the tree as the center section 11. On running the E-W 1/4 line found a 1/2" rod 2' North of the line from the center to E 1/4 corner 2634.9 which is .34' short of recorded Golden Hill plat.

5-1956 McGhie - Found the cut limestone with a drill hole on top. Corner lies 25' West of the N-S fence 6' South of the E-W fence

7-13-1970 Roger Brand, County Surveyor, (cert. filed) found limestone 6" x 8" x 24". Set CIM over 3/4" rod in place of stone.

11-9-1988 County Surveyor found CIM in good condition. Took new ties.

Note: This corner was destroyed in federal flood control project construction.

1-8-1997 Mn/DOT note from corner maintenance record: The monument was found to be obliterated. Will reset this corner.

4-19-2002 Mn/DOT survey crew found spike (set by County Surveyor as temporary corner).

5-14-2002 County Surveyor set Cast Iron Cap on 6' long telspar pipe from ties and traverse data.

10-2-2002 County Surveyor found cast iron cap on telspar pipe up 0.2' in good condition.

10-13-2004 WHKS Survey Crew found monument in good condition as described in record.

3-1-2010 Ken Manahan, Mn/DOT Crew Chief, found cast iron cap on telspar pipe in good condition.