Certificate of Location of Government Corner

ID#: 641109 **Description:** SEC CEN 11 64 **Date Set:** 9/6/2007 **County:** Olmsted

Section: 11 **Township:** 106N **Range:** 14W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 30 1/2' south of centerline of 16th St SW, 12' west of centerline of driveway for house #408 and 14' east of centerline of driveway for house #410
County Survey Disk in W side PP #8335 S 20.42'
This corner is located by GPS measurement

Corner History:

8-9-1921 C. Armstrong found and used monument.

1940 B. 103 P. 60 - Corner proven by E-West line as 2' north of true line. Measure east 2634.9, west 2634.0, S 2631.7.

4-13-1957 K. McGhie found and used monument.

6-29-1959 J. Kerr found and used monument.

9-17-1971 McGhie & Betts found and used 5/8" rod 2.00' north of center.

11-18-1975 McGhie & Betts found and used 5/8" rod 2.00' north of center.

12-12-1977 McGhie & Betts found 5/8" iron 2.00' north of center of section 11.

4-8-1980 R. Brand found and used 5/8" rod 2.00' north of center.

3-2-1981 Yaggy Associates found and used 5/8" rod 2.00' north of center.

5-19-1986 Yaggy Associates found and used 5/8" rod 2.00' north of center.

12-7-1988 County Surveyor located in traverse for City of Rochester mapping project survey. Found offset Iron.

7-1997 McGhie & Betts report the rod is gone.

9-6-2007 County Surveyor found nothing. Set a 3' telspar pipe w/CIC down 0.2' from GPS coordinates.

6-16-2009 County Surveyor found cast iron cap on telspar pipe down 0.3' in good condition.

3-31-2010 Brian Veronen, Mn/DOT LSIT, found cast iron cap on telspar pipe in good condition.